Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3549	2-Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap near CPRI Bemloi	-	added	0		4-Sep	Excellent
3550			2	Main tank Kasumpti	-	added	0		4-Sep	Excellent
3551			3	Main tank aupper dingu mandir	-	added	0		4-Sep	Excellent
3552			4	Main tank lower dingu mandir	-	added	0		4-Sep	Excellent
3553			5	Public tap laxmi narayan mandir sanjauli	-	added	0		4-Sep	Excellent
3554			6	Reservoir sanjauli outlet	-	added	11		5-Sep	unsatisfactory
3555	3-Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank sandal chakkar	-	added	0		5-Sep	Excellent
3556			2	public tank ATM corrporative bank chakkar	-	added	0		5-Sep	Excellent
3557			3	main supply sankrall niwas chakkar	-	added	0		5-Sep	Excellent
3558			4	main supply som cottage chakkar	-	added	0		5-Sep	Excellent
3559			5	main tank kasumpti	-	added	0		5-Sep	Excellent
3560			6	reservoir sanjauli outlet	-	added	0		5-Sep	Excellent
3561	4-Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Bhimakali mandir tank totu	-	added	0		6-Sep	excellent
3562			2	Yadagar tank Totu	-	added	0		6-Sep	excellent
3563			3	Public Tap charuji Bhawan lower totu	-	added	0		6-Sep	excellent
3564			4	Public Tap Totu chowk	-	added	11		7-Sep	unsatisfactory
3565			5	Kasumpti Reservoir	_	added	0		6-Sep	\
3566			6	Sanjauli Reservoir outlet	-	added	0		6-Sep	excellent

3567	5-Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla,	1	kasumpti reservior	-	added	0	-	7-Sep	Excellent
3568			2	mains field tank no. 1 outlet	-	added	0	-	7-Sep	Excellent
3569			3	mains field tank no. 2 outlet	-	added	0	-	7-Sep	Excellent
3570			4	raj bhawan kitchen	-	added	0	-	7-Sep	Excellent
3571			5	H.P sect old tank raj bhawan	-	added	0	-	7-Sep	Excellent
3572			6	sanjauli reservior outlet	-	added	0	-	7-Sep	Excellent