

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
3621	19/7/19	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpti Reservoir	added	MPN=180+	thermotolerant E.coli not detected	22/7/19	unsatisfactory
3622			2	Sector 3 Old tank Outlet (REPEAT)	added	MPN=180	thermotolerant E.coli not detected	22/7/19	unsatisfactory
3623			3	P.Tap near Goel apartment Dhingu	added	MPN=180+	thermotolerant E.coli not detected	22/7/19	unsatisfactory (adv : repeat sample)
3624			4	P.Tap near Laxmi Narayan Temple Sanjauli	added	MPN=180	thermotolerant E.coli not detected	22/7/19	unsatisfactory (adv : repeat sample)
3625			5	P.Tap near old police thana, Sanjauli	added	MPN=40	thermotolerant E.coli not detected	22/7/19	unsatisfactory (adv : repeat sample)
3626			6	Noth Oak UG tank outlet	added	MPN=180	thermotolerant E.coli not detected	22/7/19	unsatisfactory (adv : repeat sample)
3627			7	NORTH OAK O.H. TANK outlet	added	MPN=30	thermotolerant E.coli not detected	22/7/19	unsatisfactory (adv : repeat sample)
3628			8	Sanjauli Reservoir	added	MPN=90	thermotolerant E.coli not detected	22/7/19	unsatisfactory (adv : repeat sample)
3629	19-07-19	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank	added	MPN=7			
3630			2	mains field tank	added	MPN=35			unsatisfactory
3631			3	Kalaston Tank	added	MPN=3			
3632			4	Dhalli tank	added	MPN=17			unsatisfactory
3633			5	Chakkar tank	added	MPN=180+			unsatisfactory
3634			6	Knollswood tank	added	MPN=20			unsatisfactory
3635			7	Jakhoo tank rope way	added	MPN=20			unsatisfactory
3636			8	Pub tap channel-9 khalini	added	MPN=5			
3637			9	Pub-tap by pass road khalini	added	MPN=5			
3638			10	Pub-tap panchiyeta	added	MPN=5			
3639			11	Pub-tap sood bhawan khalini	added	MPN=12			
3640			12	Pub-tap kalimata mandir khalini	added	MPN=180			unsatisfactory
3641	20/07/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpti Reservoir	added	MPn = 17	thermotolerant E.coli not detected	23-07-2019	unsatisfactory
3642			2	Public tap near M.C. office New Shimla	added	MPN = 180 +	thermotolerant E.coli not detected	23-07-2019	Repeat sample advised
3643			3	Public tap near DAV School New Shimla	added	MPN = 40	thermotolerant E.coli not detected	23-07-2019	Repeat sample advised

