

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
3797	29/7/19	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpati reservoir	added	MPN=1	thermotolerant E.coli not detected	1/8/2019	satisfactory
3798			2	Sector 2 Tank, New Shimla	added	MPN=12	thermotolerant E.coli not detected	1/8/2019	Repeat sample advised
3799			3	sector 4 tank, New Shimla	added	MPN=2	thermotolerant E.coli not detected	1/8/2019	satisfactory
3800			4	sector 3 old tank, New Shimla	added	MPN=17	thermotolerant E.coli not detected	1/8/2019	Repeat sample advised
3801			5	sector 3 new tank, New Shimla	added	MPN=10	thermotolerant E.coli not detected	1/8/2019	Repeat sample advised
3802			6	public tap near Mangla Bhawan, New Shimla	added	MPN=2	thermotolerant E.coli not detected	1/8/2019	satisfactory
3803			7	Sanjauli reservoir	added	MPN=2	thermotolerant E.coli not detected	1/8/2019	satisfactory
3804			8	Dhali tank	added	MPN=0	thermotolerant E.coli not detected	1/8/2019	excellent
3805	29-07-19	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank	added	MPN=5		31-07-19	
3806			2	Mainsfield tank	added	MPN=0		31-07-19	excellent
3807			3	Kalaston Tank	added	MPN=5		31-07-19	
3808			4	Dhali tank	added	MPN=10		31-07-19	
3809			5	Chakkar tank	added	MPN=180+		31-07-19	Unsatisfactory
3810			6	Knollswood tank	added	MPN=3		31-07-19	
3811			7	Jakhoo tank ropway	added	MPN=2		31-07-19	

3812			8	Pub-tap near Apna Medical store Chotta Shimla	added	MPN=2		31-07-19	
3813			9	Pub-tap five banch jakhoo	added	MPN=3		31-07-19	
3814			10	Pub-tap dhalpur house	added	MPN=0		31-07-19	excellent
3815			11	Pub-tap baba balak tample jakhoo	added	MPN=1		31-07-19	
3816			12	Pub-tap near ropway jakhoo	added	MPN=1		31-07-19	