

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
4405	2/9/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpati reservoir	added	MPN=2	thermotolerant E.coli not detected	43594	SATISFACTORY
4406			2	public tap near Eva sales Corp.Ganj bazar	added	MPN=1	thermotolerant E.coli not detected	43594	SATISFACTORY
4407			3	Public tap near Prushartha basti Lower bazar	added	MPN =0	thermotolerant E.coli not detected	43594	EXCELLENT
4408			4	public tap near indira chowk ,lower bazar	added	MPN =0	thermotolerant E.coli not detected	43594	EXCELLENT
4409			5	public tap near Samsung store Mall road	added	MPN=3	thermotolerant E.coli not detected	43594	SATISFACTORY
4410			6	public tap near HPMC ridge	added	MPN =0	thermotolerant E.coli not detected	43594	EXCELLENT
4411			7	Ridge tank outlet	added	MPN =0	thermotolerant E.coli not detected	43594	EXCELLENT
4412			8	Sanjauli reservoir	added	MPN=3	thermotolerant E.coli not detected	43594	SATISFACTORY
4413	2/9/2019	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	ridge tank	added	MPN=00		43533	EXCELLENT
4414			2	mains field tank	added	MPN=03		43533	
4415			3	keloston tank	added	MPN=90		43533	unsatisfactory
4416			4	tavi tank	added	MPN=05		43533	
4417			5	dhali tank	added	MPN=07		43533	
4418			6	knowls wood tank	added	MPN=12		43533	unsatisfactory
4419			7	phase=3 tank	added	MPN=05		43533	
4420			8	vikasnagar tank	added	MPN=02		43533	
4421			9	pub tap sanjauli chowk	added	MPN=05		43533	
4422			10	pub tap near sbi sanjauli	added	MPN=05		43533	
4423			11	pub tap police gumti chotta shimla	added	MPN=03		43533	
4424			12	pub tap lakshi narayan chotta shimla	added	MPN=05		43533	

4425	3/9/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	P.Tap near MC office New shimla	added			43625	Repeat sample requested
4426			2	Sector 3, Old tank outlet	added	MPN=0	thermotolerant E.coli not detected	43625	excellent
4427			3	P.Tap near Mangla bhawan , new shimla	added	MPN=0	thermotolerant E.coli not detected	43625	excellent
4428			4	Sector 3, new tank	added	MPN=0	thermotolerant E.coli not detected	43625	excellent
4429			5	SECTOR 1 TANK	added	MPN=0	thermotolerant E.coli not detected	43625	excellent
4430			6	Tara mata mandir tank	added			43625	Repeat sample requested
4431			7	Kasumpati reservoir	added	MPN=1	thermotolerant E.coli not detected	43625	SATISFACTORY
4432			8	Sanjauli reservoir	added	MPN=8	thermotolerant E.coli not detected	43625	SUSPECIOUS
4433	3/9/2019	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	ridge tank	added	MPN= 05		43594	
4434			2	mains field tank	added	MPN= 05		43594	
4435			3	sanjauli chowk pub tap	added	MPN= 05		43594	
4436			4	dhali tank	added	MPN= 00		43594	EXCELLENT
4437			5	tavi tank	added	MPN= 05		43594	
4438			6	knowlls wood tank	added	MPN= 00		43594	EXCELLENT
4439			7	jakhoo tank	added	MPN= 00		43594	EXCELLENT
4440			8	pub tap brock hurts chotta shimla	added	MPN= 05		43594	
4441			9	dhalpur house pub tap	added	MPN= 05		43594	
4442			10	baba balak nath pub tap	added	MPN= 05		43594	
4443			11	five bench pub tap	added	MPN= 05		43594	
4444			12	near rooplay pub tap	added	MPN= 05		43594	
4445	4/9/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	KASUMPATI RESERVOIR	added	MPN=0	thermotolerant E.coli not detected	43655	EXCELLENT
4446			2	P.TAP NEAR LAXMI NARAYAN TEMPLE	added	MPN=3	thermotolerant E.coli not detected	43655	SATISFACTORY
4447			3	P.TAP NEAR GOEL APARTMENT DHINGU	added		thermotolerant E.coli not detected	43655	Repeat sample requested

4448			4	DHINGU MANDIR TANK	added	MPN=0	thermotolerant E.coli not detected	43655	EXCELLENT
4449			5	P.TAP NEAR OLD POLICE THANA SANJAULI	added	MPN=0	thermotolerant E.coli not detected	43655	EXCELLENT
4450			6	NORTH OAK U.G. TANK	added	MPN=0	thermotolerant E.coli not detected	43655	EXCELLENT
4451			7	NORTH OAK O.H. TANK	added	MPN=0	thermotolerant E.coli not detected	43655	EXCELLENT
4452			8	SANJAULI RESERVOIR	added	MPN=0	thermotolerant E.coli not detected	43655	EXCELLENT
4453	4/9/2019	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	RIDGE TANK	added	MPN=1		43625	
4454			2	mains field tank	added	MPN=2		43625	
4455			3	KELASTON TANK	added	MPN=0		43625	EXCELLENT
4456			4	DHALI TANK	added	MPN=0		43625	EXCELLENT
4457			5	PUB TAP DHANDA CHOWK	added	MPN=0		43625	EXCELLENT
4458			6	PHASE =3 TANK	added	MPN=3		43625	
4459			7	JAKHOO ROPEWAY TANK	added	MPN=2		43625	
4460			8	pub tap brock hurts chotta shimla	added	MPN=2		43625	
4461			9	PUB TAP BABA KHAN STORE	added	MPN=5		43625	
4462			10	PUB TAP SUJI JANE	added	MPN=5		43625	
4463			11	PUB TAP PURSHARLF BASTI	added	MPN=5		43625	
4464			12	PUB TAP INDIRA CHOWK	added	MPN=5		43625	