

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
4741	20/09/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpti reservoir	added	MPN =2	thermotolerant E.coli not detected	23/9/2019	SATISFACTORY
4742			2	Advance study tank Summer hill	added	MPN=35	thermotolerant E.coli not detected	23/9/2019	ADV : REPEAT SAMPLE
4743			3	Public tap near summer hill chowk	added	MPN=12	thermotolerant E.coli not detected	23/9/2019	ADV : REPEAT SAMPLE
4744			4	Public tap near Raj dairy Summerhill bazar	added	MPN=4	thermotolerant E.coli not detected	23/9/2019	ADV : REPEAT SAMPLE
4745			5	Summer hill Bazar tank	added	MPN=9	thermotolerant E.coli not detected	23/9/2019	ADV : REPEAT SAMPLE
4746			6	Public tap near lower Summerhill	added	MPN=3	thermotolerant E.coli not detected	23/9/2019	SATISFACTORY
4747			7	Public tap near Totu chowk	added	MPN=5	thermotolerant E.coli not detected	23/9/2019	ADV : REPEAT SAMPLE
4748			8	Sanjauli reservoir	added	MPN=17	thermotolerant E.coli not detected	23/9/2019	UNSATISFACTORY
4749	20/9/19	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank	added	MPN=1		22/9/19	
4750			2	Pub-tap Ridge HPMC	added	MPN=14		22/9/19	unatisfactory
4751			3	Sowndon pump housre	added	MPN=5		22/9/19	
4752			4	Pub-tap near UCO Bank dhalli	added	MPN=2		22/9/19	
4753			5	tavi tank	added	MPN=14		22/9/19	unatisfactory
4754			6	Phase-3 tank	added	MPN=2		22/9/19	
4755			7	Jakhoo tank ropeway	added	MPN=1		22/9/19	
4756			8	Pub-tap brock host	added	MPN=3		22/9/19	
4757			9	Pub-tap yadgar	added	MPN=35		22/9/19	unsatisfactory
4758			10	Pub-tap totu chowk	added	MPN=8		22/9/19	
4759			11	Pub-tap near SBI ATM	added	MPN=5		22/9/19	
4760			12	pub-tap PNB ATM	added	MPN=5		22/9/19	
4761	21/9/19	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpati reservoir	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4762			2	Engine ghar tank	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4763			3	Public tap near Mehta parking Engine ghar	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4764			4	public tap near Laxmi narayam temple	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4765			5	public tap near old police thana, Sanjauli	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4766			6	north Oak UG tank	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT

4767			7	north Oak OH tank	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4768			8	Sanjauli reservoir	added	MPN=0	thermotolerant E.coli not detected	24/9/19	EXCELLENT
4769	21/9/19	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank	added	MPN=0		23/9/2019	EXCELLENT
4770			2	Pub-tap Ridge HPMC	added	MPN=0		23/9/2019	EXCELLENT
4771			3	Kelaston tank	added	MPN=2		23/9/2019	
4742			4	Dhalli tank	added	MPN=0		23/9/2019	EXCELLENT
4773			5	Pub-tap yadgar	added	MPN=13		23/9/2019	UNSATISFACTORY
4774			6	Phase-3 tank	added	MPN=0		23/9/2019	EXCELLENT
4775			7	Jakhoo tank ropeway	added	MPN=0		23/9/2019	EXCELLENT
4776			8	Pub-tap near Police gumti Chotta Shimla	added	MPN=1		23/9/2019	
4777			9	Pub-tap near Apna Medical store Chotta Shimla	added	MPN=3		23/9/2019	
4778			10	Pub-tap servent quarter chotta shimla	added	MPN=1		23/9/2019	
4779			11	Pub-tap brock horst-1	added	MPN=0		23/9/2019	EXCELLENT
4780			12	Pub-tap brock herst near gugga mandir	added	MPN=3			