

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.	333	SODIUM THIOSULPHA	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT
29/07/2020	4011	<b>Samples received from A.E. , SJPN</b>	1	KASUMPTI RESERVOIR	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4012		2	SAKRALA TANK	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4013		3	Phase III Tank No. 1	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4014		4	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4015		5	PUBLIC TAP NEAR SERVANT QUARTERS KNOLLS WOOD	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4016		6	KNOLLSWOOD TANK	added	thermotolerant E.coli not detected	08-01-20	SUSPICIOUS
	4017		7	Public tap near Police Gumati Chotta Shimla	added	thermotolerant E.coli not detected	08-01-20	SUSPICIOUS
	4018		8	Public tap near Apna Medical store Chotta Shimla	added	thermotolerant E.coli not detected	08-01-20	SUSPICIOUS
	4019		9	MAINSFIELD TANK	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4020		10	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	08-01-20	uNSATISFACTORY
	4021		11	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	08-01-20	SUSPICIOUS
	4022		12	BHIMAKALI TANK	added	thermotolerant E.coli not detected	08-01-20	UNSATISFACTORY
	4023		13	103 TANK	added	thermotolerant E.coli not detected	08-01-20	UNSATISFACTORY
	4024		14	BHARARI TANK	added	thermotolerant E.coli not detected	08-01-20	Satisfactory
	4025		15	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	08-01-20	SUSPICIOUS
	4026		16	GiRI INLET	added	thermotolerant E.coli not detected	08-01-20	unSATISFACTORY
	4027		17	GuMMA INLET	added	thermotolerant E.coli not detected	08-01-20	Satisfactory
	4028		18	Dhalli Catchment inlet	added	thermotolerant E.coli not detected	08-01-20	satisfactory
	4029		19	Churat and Jagrati inlet	added	thermotolerant E.coli not detected	08-01-20	SUSPICIOUS
	4030		20	Dhalli tank outlet	added		08-01-20	Excellent
30/07/2020	4031	<b>Samples received from A.E. , SJPN</b>	1	KASUMPATI RESERVOIR	added		08-02-20	Excellent
	4032		2	PHASE 3 TANK NO 1	added		08-02-20	Excellent
	4033		3	TARA MATA MANDIR TANK	added		08-02-20	Excellent

	4034		4	MAINSFIELD TANK	added		08-02-20	Excellent
	4035		5	PUBLIC TAP NEAR FIVE BENCH	added		08-02-20	Excellent
	4036		6	PUBLIC TAP NEAR DHAULPUR HOUSE JAKHU	added		08-02-20	Excellent
	4037		7	JAKHU tank near HANuman Temple	added		08-02-20	Excellent
	4038		8	RIDGE TANK OUTLET	added		08-02-20	Excellent
	4039		9	SUPPLY NEAR HOLLY LODGE	added		08-02-20	Excellent
	4040		10	SUPPLY NEAR LAHNU BHAWAN	added		08-02-20	Excellent
	4041		11	Public tap near Charlie mount Jakhu	added	thermotolerant E.coli not detected	08-02-20	satisfactory
	4042		12	CHAKKAR TANK	added		08-02-20	Excellent
	4043		13	PHAGLI TANK	added		08-02-20	Excellent
	4044		14	KLESTAN TANK	added		08-02-20	Excellent
	4045		15	SANJAULI RESERVOIR	added		08-02-20	Excellent
	4046		16	GIRI INLET	added		08-02-20	Excellent
	4047		17	GUMMA INLET	added	thermotolerant E.coli not detected	08-02-20	SaTISFACTORY
	4048		18	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	08-02-20	SaTISFACTORY
	4049		19	PUBLIC TAP NEAR DHALLI CHOWK	added		08-02-20	Excellent
	4050		20	PUBLIC TAP NEAR SANJAULI CHOWK	added	thermotolerant E.coli not detected	08-02-20	SaTISFACTORY
31/07/20	4051	<b>Samples received from A.E. , SJPN</b>	1	KASUMPTI RESERVOIR	added		08-03-20	Excellent
	4052		2	MAINSFIELD TANK	added	thermotolerant E.coli not detected	08-03-20	Satisfactory
	4053		3	JAKHU tank near HANuman Temple	added		08-03-20	Excellent
	4054		4	PUBLIC TAP NEAR EVA SALES CORPORATION GANJ BAZAR	added	thermotolerant E.coli not detected	08-03-20	Satisfactory
	4055		5	Public tap naer Prushartha basti	added	thermotolerant E.coli not detected	08-03-20	Satisfactory
	4056		6	Public tap near Sabji mandi Lower bazar	added	thermotolerant E.coli not detected	08-03-20	Satisfactory
	4057		7	Public tap near Indra chowk Lower bazar	added		08-03-20	Excellent
	4058		8	Public tap near Samsung shop mall road	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4059		9	PUBLIC TAP NEAR KHADI BANDHAR MALL ROAD	added	thermotolerant E.coli not detected	08-03-20	SATISfactory
	4060		10	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	08-03-20	Satisfactory
	4061		11	Fingask tank	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory

	4062		12	103 TANK	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4063		13	ADVANCE STUDY TANK	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4064		14	BHARARI TANK	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4065		15	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	08-03-20	SUSPICIOUS
	4066		16	Churat and Jagrati inlet	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4067		17	Dhalli tank outlet	added	thermotolerant E.coli not detected	08-03-20	SUSPICIOUS
	4068		18	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4069		19	GIRI INLET	added	thermotolerant E.coli not detected	08-03-20	Unsatisfactory
	4070		20	GuMMA INLET	added	thermotolerant E.coli not detected	08-03-20	SUSPICIOUS
08-01-20	4071	<b>Samples received from A.E. , SJPN</b>	1	KASUMPTI RESERVOIR	added		08-04-20	Excellent
	4072		2	Phase III tank No. 1	added	thermotolerant E.coli not detected	08-04-20	Satisfactory
	4073		3	TARA MATA MANDIR TANK	added		08-04-20	Excellent
	4074		4	MAINSFIELD TANK	added		08-04-20	Excellent
	4075		5	JAKhu tank near HAnuman Temple	added		08-04-20	Excellent
	4076		6	RIDGE TANK OUTLET	added		08-04-20	Excellent
	4077		7	PUBLIC TAP NEAR GOVT SCHOOL PHAGLI	added	thermotolerant E.coli not detected	08-04-20	SUSPICIOUS
	4078		8	PHAGLI TANK	added		08-04-20	Excellent
	4079		9	Public tap near Tibetan colony Nabha	added	thermotolerant E.coli not detected	08-04-20	Satisfactory
	4080		10	Public tap near Kali Kothi Tutikandi	added		08-04-20	Excellent
	4081		11	TUTIKANDI TANK	added	thermotolerant E.coli not detected	08-04-20	satisfactory
	4082		12	103 TANK	added	thermotolerant E.coli not detected	08-04-20	satisfactory
	4083		13	BHIMAKALI TANK	added	thermotolerant E.coli not detected	08-04-20	Satisfactory
	4084		14	KLESTAN TANK	added		08-04-20	Excellent
	4085		15	SANJAULI RESERVOIR	added		08-04-20	Excellent
	4086		16	GIRI INLET	added		08-04-20	Excellent
	4087		17	GUMMA INLET	added	thermotolerant E.coli not detected	08-04-20	Satisfactory
	4088		18	Dhalli Catchment inlet	added		08-04-20	Excellent

	4089		19	Churat and Jagrati inlet	added		08-04-20	Excellent
	4090		20	Dhalli tank outlet	added		08-04-20	Excellent
	4091		21	Supply near Range view building Lower Kethu	added		08-04-20	Excellent