

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.	333	SODIUM THIOSULPHATE	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT
16/9/2020	4992	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added	Thermotolerant E.coli not detected	19/9/2020	SATISFACTORY
	4993		2	P.TAP NEAR A-1 BLOCK VIKAS NAGAR	added		19/9/2020	Excellent
	4994		3	PHASE 3 TANK NO.1	added		19/9/2020	Excellent
	4995		4	SUPPLY NEAR SOOD BHAWAN BHAGWATI NAGAR	added	Thermotolerant E.coli not detected	19/9/2020	SATISFACTORY
	4996		5	P.TAP NEAR LOWER BYPASS ROAD	added		19/9/2020	Excellent
	4997		6	P.TAP NEAR KHALINI CHOWK	added	detected	19/9/2020	SATISFACTORY
	4998		7	P.TAP NEAR SERVANT QUARTER KNOLLSWOOD	added		19/9/2020	Excellent
	4999		8	P.TAP NEAR APNA MEDICAL STORE CHOTTA SHIMLA	added		19/9/2020	Excellent
	5000		9	SDA KASUMPTI TANK	added	detected	19/9/2020	SUSPICIOUS
	5001		10	P.TAP NEAR DURGA COTTAGE SDA	added	Thermotolerant E.coli not detected	19/9/2020	UNSATISFACTORY
	5002		11	MAINSFIELD TANK	added	detected	19/9/2020	SUSPICIOUS
	5003		12	JAKHU TANK NEAR HANUMAN TEMPLE	added	Thermotolerant E.coli not detected	19/9/2020	SUSPICIOUS
	5004		13	PHAGLI TANK	added	detected	19/9/2020	SUSPICIOUS
	5005		14	KLESTON TANK	added	detected	19/9/2020	SATISFACTORY
	5006		15	DHALLI CATCHMENT INLET	added		19/9/2020	Excellent
	5007		16	CHURAT AND JAGRITI INLET	added	detected	19/9/2020	SATISFACTORY
	5008		17	DHALLI TANK OUTLET	added	detected	19/9/2020	UNSATISFACTORY
	5009		18	SANJAULI RESERVOIR	added	detected	19/9/2020	SATISFACTORY
	5010		19	GI RI INLET	added	detected	19/9/2020	SUSPICIOUS
	5011		20	GU MMA INLET	added		19/9/2020	Excellent
17/9/2020	5012	Samples received from A.E. , SJPN Ltd.	1	KUSUMPTI RESERVOIR	added		20/9/2020	Excellent
	5013		2	TARA MATA MANDIR TANK	added		20/9/2020	Excellent
	5014		3	MAINSFIELD TANK	added		20/9/2020	Excellent
	5015		4	JAKHU TANK NEAR HAMU,AN MANDIR	added		20/9/2020	Excellent
	5016		5	P.TAP NEAR KHADI BHANDER MALL MANDIR SHIMLA	added		20/9/2020	Excellent
	5017		6	P.TAP NEAR SAMSUNG SHOP MALL ROAD SHIMLA	added		20/9/2020	Excellent
	5018		7	P.TAP NEAR HPMC RIDGE	added		20/9/2020	Excellent
	5019		8	FINGAS TANK NO.1	added		20/9/2020	Excellent
	5020		9	103 TANK	added		20/9/2020	Excellent
	5021		10	BHIMAKALI TANK	added	detected	20/9/2020	SUSPICIOUS
	5022		11	P.TAP NEAR COUNCILLOR HOUSE RULDUBHATTA	added		20/9/2020	Excellent
	5023		12	P.TAP NEAR SHIV COTTAGE RULDUBHATA	added	Thermotolerant E.coli not detected	20/9/2020	SUSPICIOUS

	5024		13	P.TAP NEAR SHYAM SINGH BUILDING RULDUBHATA	added		20/9/2020	Excellent
	5025		14	BHARARI TANK	added	detected	20/9/2020	SUSPICIOUS
	5026		15	SANJAULI RESERVOIR	added		20/9/2020	Excellent
	5027		16	GI RI INLET	added	detected	20/9/2020	SATISFACTORY
	5028		17	GUMMA INLET	added	detected	20/9/2020	SATISFACTORY
	5029		18	DHALLI CATCHMENT INLET	added	detected	20/9/2020	SATISFACTORY
	5030		19	CHURAT AND JAGRITI INLET	added	detected	20/9/2020	SATISFACTORY
	5031		20	DHALLI TANK OUTLET	added	detected	20/9/2020	SATISFACTORY
18/9/2020	5032	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		21/9/2020	Excellent
	5033		2	PHASE III TANK NO.1	added		21/9/2020	Excellent
	5034		3	MAINSFIELD TANK	added		21/9/2020	Excellent
	5035		4	JAKHU TANK NEAR HANUMAN TEMPLE	added		21/9/2020	Excellent
	5036		5	P.TAP NEAR DHOBI GHAT ANADALE	added		21/9/2020	Excellent
	5037		6	P.TAP NEAR LUXMI NIWAS	added		21/9/2020	Excellent
	5038		7	P.TAP NEAR BIHARI LAL COTTAGE, ANNADALE	added		21/9/2020	Excellent
	5039		8	P.TAP NEAR KRISHNA HILL, ANNADALE	added	Thermotolerant E.coli not detected	21/9/2020	SATISFACTORY
	5040		9	P.TAP NEAR KALA SADAN ANADALE	added	Thermotolerant E.coli not detected	21/9/2020	UNSATISFACTORY
	5041		10	P.TAP NEAR GRACE VILLA ANADALE	added	Thermotolerant E.coli not detected	21/9/2020	SATISFACTORY
	5042		11	TARAHALL TANK	added	detected	21/9/2020	SATISFACTORY
	5043		12	TUTIKANDI TANK	added	detected	21/9/2020	UNSATISFACTORY
	5044		13	CHAKKAR TANK	added	detected	21/9/2020	UNSATISFACTORY
	5045		14	KLESTON TANK	added	detected	21/9/2020	UNSATISFACTORY
	5046		15	SANJAULI RESERVOIR	added	detected	21/9/2020	SUSPICIOUS
	5047		16	GI RI INLET	added	detected	21/9/2020	SATISFACTORY
	5048		17	GUMMA INLET	added	detected	21/9/2020	SUSPICIOUS
	5049		18	DHALL CATCHMENT INLET	added	detected	21/9/2020	UNSATISFACTORY
	5050		19	CHURAT AND JAGRITI INLET	added	detected	21/9/2020	SUSPICIOUS
	5051		20	DHALLI TANK OUTLET	added	detected	21/9/2020	UNSATISFACTORY
19/9/2020	5052	Samples received from A.E. , SJPN Ltd.	1	SANJAULI RESERVOIR	added		22/9/2020	Excellent
	5053		2	TARA MATA MANDIR TANK	added		22/9/2020	Excellent
	5054		3	MAINSFIELD TANK	added		22/9/2020	Excellent
	5055		4	JAKHU TANK NERA HANUMAN TEMPLE	added		22/9/2020	Excellent
	5056		5	PHAGLI TANK	added		22/9/2020	Excellent
	5057		6	P.TAP NEAR TIBETAN COLONY NABHA	added		22/9/2020	Excellent
	5058		7	P.TAP NEAR RAJ DAIRY SUMMERHILL	added		22/9/2020	Excellent
	5059		8	SUMMER HILL BAJAR TANK	added		22/9/2020	Excellent

	5060		9	P.TAP NEAR LOWER SUMMER HILL	added		22/9/2020	Excellent
	5061		10	P.TAP NEAR SUMMERHILL CHOWK	added		22/9/2020	Excellent
	5062		11	ADVANCE STUDY TANK	added		22/9/2020	Excellent
	5063		12	BHARARI TANK	added		22/9/2020	Excellent
	5064		13	P.TAP NEAR MC OFFICE SANJAULI	added	Thermotolerant E.coli not detected	22/9/2020	SATISFACTORY
	5065		14	SANJAULI RESERVOIR	added		22/9/2020	Excellent
	5066		15	GiRI INLET	added		22/9/2020	Excellent
	5067		16	GUMMA INLET	added		22/9/2020	Excellent
	5068		17	P.TAP NEAR DHALLI CHOWK	added		22/9/2020	Excellent
	5069		18	DHALLI CATCHMENT INLET	added	detected	22/9/2020	UNSATISFACTORY
	5070		19	CHURAT AND JAGRITI INLET	added		22/9/2020	Excellent
	5071		20	DHALLI TANK OUTLET	added		22/9/2020	Excellent
20/9/2020	5072	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		23/9/2020	Excellent
	5073		2	SDA KASUMPTI TANK	added		23/9/2020	Excellent
	5074		3	P.TAP NEAR DURGA COTTAGE SDA COMPLEX KASUMPATI	added		23/9/2020	Excellent
	5075		4	PHASE III TANK NO.1	added		23/9/2020	Excellent
	5076		5	MAINSFIELD TANK	added		23/9/2020	Excellent
	5077		6	JAKHU TANK NEAR HANUMAN TEMPLE	added		23/9/2020	Excellent
	5078		7	P.TAP NEAR SANJAULI CHOWK	added		23/9/2020	Excellent
	5079		8	P.TAP NEAR OLD POLICE THANA SANJAULI	added		23/9/2020	Excellent
	5080		9	P.TAP NEAR LUXMI NARAYAN TEMPLE SANJAULI	added		23/9/2020	Excellent
	5081		10	SANJAULI RESERVOIR	added		23/9/2020	Excellent
	5082		11	GiRI INLET	added		23/9/2020	Excellent
	5083		12	GuMMA INLET	added		23/9/2020	Excellent
	5084		13	P.TAP NEAR BHAGWATI NIWAS LAKKAR BAZAAR	added		23/9/2020	Excellent
	5085		14	BHIMAKALI TANK	added		23/9/2020	Excellent
	5086		15	103 TANK	added		23/9/2020	Excellent
	5087		16	TUTIKANDI TANK	added		23/9/2020	Excellent
	5088		17	DHALLI CATCHMENT INLET	added		23/9/2020	Excellent
	5089		18	CHURAT AND JAGROTI INLET	added		23/9/2020	Excellent
	5090		19	DHALLI TANK OUTLET	added		23/9/2020	Excellent
	5091		20	KALYANI TANK CHARABRA	added		23/9/2020	Excellent
21/9/2020	5092	Samples received from A.E. , SJPN Ltd.	1	KUSUMPTI RESERVOIR	added	Thermotolerant E.coli not detected	24/9/2020	SATISFACTORY
	5093		2	PHASE 3 TANK NUMBER 1	added	detected	24/9/2020	SATISFACTORY
	5094		3	PHASE 3 TANK NUMBER 3	added	detected	24/9/2020	SATISFACTORY
	5095		4	TARA MATA MANDIR TANK	added	detected	24/9/2020	SATISFACTORY
	5096		5	SECTOR 1 TANK, NEW SHIMLA	added	detected	24/9/2020	SUSPICIOUS

	5097		6	P.TAP NEAR MC OFFICE NEW SHIMLA	added	Thermotolerant E.coli not detected	24/9/2020	SUSPICIOUS
	5098		7	SECTOR 4 TANK NEW SHIMLA	added	detected	24/9/2020	SATISFACTORY
	5099		8	SECTOR 2 TANK NEW SHIMLA	added	detected	24/9/2020	SATISFACTORY
	5100		9	MAINSFIELD TANK	added	detected	24/9/2020	UNSATISFACTORY
	5101		10	JAKHU TANK NEAR HANUMAN TEMPLE	added	Thermotolerant E.coli not detected	24/9/2020	SATISFACTORY
	5102		11	BHIMAKALI TANK	added	detected	24/9/2020	UNSATISFACTORY
	5103		12	P.TAP NEAR SHIV COTTAGE RULDUBHATA	added	Thermotolerant E.coli not detected	24/9/2020	UNSATISFACTORY
	5104		13	KLESTON TANK	added	detected	24/9/2020	UNSATISFACTORY
	5105		14	BHARARI TANK	added	detected	24/9/2020	SUSPICIOUS
	5106		15	DHALLI CATCHMENT INLET	added	detected	24/9/2020	UNSATISFACTORY
	5107		16	CHURAT AND JAGRITI INLET	added	detected	24/9/2020	UNSATISFACTORY
	5108		17	DHALLI TANK OUTLET	added	detected	24/9/2020	SUSPICIOUS
	5109		18	SANJAULI RESERVOIR	added	detected	24/9/2020	SUSPICIOUS
	5110		19	GI RI INLET	added	detected	24/9/2020	SUSPICIOUS
	5111		20	GUMMA INLET	added	detected	24/9/2020	SATISFACTORY