

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1583	9-Oct		1	Main Tank Kasumpati	-	Added	0	-	11-Oct	Excellent
1584			2	Public Tap Lakshmi Narayan Mandir Kasumpati Bazar	-	Added	0	-		Excellent
1585			3	Main Tank Badda Jakhu Temple	-	Added	0	-		Excellent
1586			4	Main Tank Small Jakhu Temple	-	Added	0	-		Excellent
1587			5	Reservoir Sanjauli Outlet	-	Added	0	-		Excellent
1588			6	Gumma Inlet Sanjauli Reservoir	-	-	0	-	-	Excellent
1589			7	Giri Inlet Sanjauli Reservoir	-	Added	0	-		Excellent
1590	10-Oct	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Main Tap Middle Bazaar		Added	0	-	12-Oct	Excellent
1591			2	Public Tap Near Lower Bazaar Tunnel		Added	0	-		Excellent
1592			3	Public Tap Ram Mandir Ram Bazaar		Added	0	-		Excellent
1593			4	Water ATM Machine Old Bus Stand		Added	0	-		Excellent
1594			5	Main Tank Kasumpti		Added	0	-		Excellent
1595			6	Main Tank Sanjauli Outlet		Added	0	-		Excellent
1596			7	Main Tank Sanjauli Guma (Inlet)		Added	0	-		Excellent
1597			8	Main Tank Giri Inlet		Added	0	-		Excellent