

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
69	1-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Sanjauli Inlet Guma (Tap water)	-	Added				Technical failure (kindly send a repeat sample)
70			2	Sanjauli Chowk (Tap water)	-	Added				Technical failure (kindly send a repeat sample)
71			3	Knollswood Tank	-	Added				Technical failure (kindly send a repeat sample)
72			4	VikasNagar Near C-41 Tank	-	Added				Technical failure (kindly send a repeat sample)
73			5	H.P.Seel Tank	-	Added				Technical failure (kindly send a repeat sample)
74			6	Kasumpti Reservoir	-	Added				Technical failure (kindly send a repeat sample)
75			7	Ridge Tap Water	-	Added				Technical failure (kindly send a repeat sample)
76			8	Khalini (Tap water)	-	Added				Technical failure (kindly send a repeat sample)
77	2-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Ridge Tap Water	-	Added				In Process
78			2	Sanjauli Inlet Giri	-	Added				In Process
79			3	Sanjauli Chowk (Tap water)	-	Added				In Process
80			4	Kasumpti Reservoir	-	Added				In Process

81			5	New Shimla Seel I (Tank)	-	Added	In Process
82			6	New Shimla Seel II (Tank)	-	Added	In Process
83			7	New Shimla Seel III (Tank)	-	Added	In Process
84			8	New Shimla Seel IV (Tank)	-	Added	In Process
85	3-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Ridge Tap Water	-	Added	In Process
86			2	Sanjauli Inlet Giri	-	Added	In Process
87			3	Sanjauli Inlet Guma	-	Added	In Process
88			4	Sanjauli Chowk	-	Added	In Process
89			5	Kasumpti Reservoir	-	Added	In Process
90			6	H.P.W.D Tank Kasumpti	-	Added	In Process
91			7	Kasumpti Chowk Public Tap	-	Added	In Process