

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
234	22-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Kasumpti Reservoir	-	Added	0	-	24-Mar	Excellent
235			2	Vikas nagar public Tap	-	Added	0	-	24-Mar	Excellent
236			3	Sanjauli Inlet Guma	-	Added	3	-	24-Mar	satisfactory
237			4	Sanjauli Inlet Giri	-	Added	0	-	24-Mar	Excellent
238			5	Sanjauli reservoir outlet	-	Added	7	-	24-Mar	unsatisfactory
239			6	Ridge Tap water	-	Added	0	-	24-Mar	Excellent
240	22-Mar	sample received from BMOMashobra	7	pump house shrula under water scheme malyana sample 1	-	Added	0	-	24-Mar	Excellent
241			8	pump house shrula under water scheme malyana sample 2 (raw water)	-	not Added	180	-	24-Mar	unsatisfactory
242	23-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public Tap Khalini Chowk	-	Added	In Process			
243			2	New shimla sec3 Tank	-	Added	In Process			
244			3	Kaumpti Tank	-	Added	In Process			
245			4	Sanjauli Inlet Giri	-	Added	In Process			
246			5	Sanjauli Inlet Guma	-	Added	In Process			
247			6	Sanjauli reservoir outlet	-	Added	In Process			
248	24-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	power House main Tank	-	Added	In Process			
249			2	Lower chakkar main Tank	-	Added	In Process			
250			3	Main tank kasumpti	-	Added	In Process			
251			4	Giri outlet main line	-	Added	In Process			
252			5	Guma main line out let	-	Added	In Process			
253			6	sanjauli main reservoir tank	-	Added	In Process			