

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
254	25-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	baluganj chowk tank	-	Added	0	-	27-Mar	Excellent
255			2	summer hill tank	-	Added	0	-	27-Mar	Excellent
256			3	kasumpti main tank	-	Added	0	-	27-Mar	Excellent
257			4	Sanjauli Inlet Giri	-	Added	0	-	27-Mar	Excellent
258			5	Sanjauli Inlet Guma	-	Added	0	-	27-Mar	Excellent
259			6	Sanjauli reservior outlet main tank	-	Added	0	-	27-Mar	Excellent
260	26-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	churat outlet	-	Added				In Process
261			2	dingoo main tank sanjauli	-	Added				In Process
262			3	Kaumpti Tank	-	Added				In Process
263			4	Giri outlet main line	-	Added				In Process

264			5	Guma main line out let	-	Added	In Process
265			6	Sanjauli reservior outlet main tank	-	Added	In Process
266	sample received fromBM		7	naldera area inlet	-	Added	In Process
267			8	naldera area outlet	-	Added	In Process
268	27-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	kasumpti main tank	-	Added	In Process
269			2	SDAcomple main tank kasumpti	-	Added	In Process
270			3	main tank raj bhavan chota shimla	-	Added	In Process
271			4	Giri inlet	-	Added	In Process
272			5	Guma in let	-	Added	In Process
273			6	Sanjauli reservior outlet main tank	-	Added	In Process