

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
168	13-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Kesleston Tank	-	Added	0	-	15-Mar	Excellent
169			2	Phase III Near Police chowki Tank	-	Added	In Process			
170			3	Phase III Tank near Block 6,7	-	Added	25	-	15-Mar	Unsatisfactory
171			4	Ridge Tap Water	-	Added	0	-	15-Mar	Excellent
172			5	Kasumpti Reservoir	-	Added	0	-	15-Mar	Excellent
173			6	Sanjauli Reservoir Outlet Tapwater	-	Added	0	-	15-Mar	Excellent
174			7	Sanjauli Inlet Guma	-	Added	90	-	15-Mar	Unsatisfactory
175			8	Sanjauli Inlet Giri	-	Added	In Process			
176	14-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge Tap Water	-	Added	In Process			
177			2	Sanjauli Reservoir	-	Added	In Process			
178			3	Sanjauli Inlet Giri	-	Added	In Process			
179			4	North Oak (O.H)	-	Added	In Process			
180			5	North Oak (U.G)	-	Added	In Process			
181			6	Kasumpti Reservoir	-	Added	In Process			
182			7	Mains Field Tank I	-	Added	In Process			
183			8	Mains Field Tank II	-	Added	In Process			

184	15-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Kasumpti Reservoir	-	Added	In Process
185			2	Engine Ghar Tank	-	Added	In Process
186			3	Bangala Colony Tank	-	Added	In Process
187			4	Bangala Colony Tapwater	-	Added	In Process
188			5	Sanjauli Reservoir	-	Added	In Process
189			6	Sanjauli Inlet Guma	-	Added	In Process
190			7	Sanjauli Inlet Giri	-	Added	In Process
191			8	Ridge Tap Water	-	Added	In Process