

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
303	2-Apr	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	kasumpti main tank	-	Added	0	-	04-Apr	Excellent
304			2	sanjauli inlet giri	-	Added	0	-	04-Apr	Excellent
305			3	sanjauli inlet gumma	-	Added	0	-	04-Apr	Excellent
306			4	sanjauli tank outlet	-	Added	0	-	04-Apr	Excellent
307			5	Main tank Engine ghar	-	Added	0	-	04-Apr	Excellent
308			6	main tank Bangala colony	-	Added	0	-	04-Apr	Excellent
309	3-Apr	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank Kamana Devi Mandir	-	Added				In Process
310			2	Main Tank Ridge	-	Added				In Process
311			3	kasumpti main tank	-	Added				In Process
312			4	sanjauli inlet giri	-	Added				In Process
313			5	sanjauli inlet gumma	-	Added				In Process
314			6	Main tank Sanjauli outlet	-	Added				In Process
315	4-Apr	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	kasumpti main tank	-	Added				In Process
316			2	Main tank shekhla Parimahal	-	Added				In Process
317			3	IAS Colony Sargreen Panthaghati	-	Added				In Process
318			4	Giri inlet main line	-	Added				In Process
319			5	gumma inlet main line	-	Added				In Process
320			6	Main tank Sanjauli outlet	-	Added				In Process