

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
512	3-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	0	-	5-May	Excellent
513			2	main tank kasumpti	-	Added	0	-	5-May	Excellent
514			3	main tank dingu mandir	-	Added	0	-	5-May	Excellent
515			4	ddhalli filter	-	Added	0	-	5-May	Excellent
516			5	main tank reservior sanjauli outlet	-	Added	0	-	5-May	Excellent
517			6	sanjauli inlet guma	-	Added	0	-	5-May	Excellent
518			7	sanjauli inlet giri	-	Added	0	-	5-May	Excellent
519	4-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank ridge	-	Added	In Process			
520			2	main tank kasumpti	-	Added	In Process			
521			3	Main tank Engine ghar	-	Added	In Process			
522			4	main tank reservior sanjauli outlet	-	Added	In Process			
523			5	sanjauli inlet guma	-	Added	In Process			
524			6	sanjauli inlet giri	-	Added	In Process			
525	5-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	In Process			

526			2	main tank kasumpti	-	Added	In Process
527			3	Basant Vihar StorageTank Ram Ground	-	Added	In Process
528			4	Vikas nagar tank	-	Added	In Process
529			5	sanjauli resrvior outlet	-	Added	In Process
530			6	sanjauli inlet guma	-	Added	In Process
531			7	sanjauli inlet giri	-	Added	In Process