

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
519	4-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank ridge	-	Added	0	-	06-May	Excellent
520			2	main tank	-	Added	0	-	06-May	Excellent
521			3	Main tank	-	Added	0	-	06-May	Excellent
522			4	main tank reservior	-	Added	0	-	06-May	Excellent
523			5	sanjauli inlet	-	Added	0	-	06-May	Excellent
524			6	sanjauli inlet giri	-	Added	0	-	06-May	Excellent
525	5-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	In Process			
526			2	main tank kasumpti	-	Added	In Process			
527			3	Basant Vihar Storage Tank Ram Ground	-	Added	In Process			
528			4	Vikas nagar	-	Added	In Process			
529			5	sanjauli	-	Added	In Process			
530			6	sanjauli inlet	-	Added	In Process			
531			7	sanjauli inlet giri	-	Added	In Process			
532	6-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	In Process			

533			2	main tank kasumpti	-	Added	In Process
534			3	tank IS colony	-	Added	In Process
535			4	bangala colony sanjauli tank	-	Added	In Process
536			5	sanjauli inlet	-	Added	In Process
537			6	sanjauli inlet giri	-	Added	In Process
538			7	main tank reservior	-	Added	In Process