

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
532	6-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	0	-	08-May	Excellent
533			2	main tank kasumpti	-	Added	0	-	08-May	Excellent
534			3	tank IS colony sargeen	-	Added	0	-	08-May	Excellent
535			4	bangala colony sanjauli tank	-	Added	0	-	08-May	Excellent
536			5	sanjauli inlet guma	-	Added	0	-	08-May	Excellent
537			6	sanjauli inlet giri	-	Added	0	-	08-May	Excellent
538			7	main tank reservior sanjauli outlet	-	Added	0	-	08-May	Excellent
539	7-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added				In Process
540			2	main tank bharari	-	Added				In Process
541			3	main tank kalston	-	Added				In Process
542			4	main tank kasumpti	-	Added				In Process
543			5	main tank reservior sanjauli	-	Added				In Process
544			6	sanjauli inlet guma	-	Added				In Process
545			7	sanjauli inlet giri	-	Added				In Process

546	8-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	In Process
547			2	chotta tank Fhingas	-	Added	In Process
548			3	badha tank Fhinghas	-	Added	In Process
549			4	main tank kasumpti	-	Added	In Process
550			5	sanjauli inlet guma(inlet)	-	Added	In Process
551			6	sanjauli inlet giri(inlet)	-	Added	In Process