

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
559	10-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	0	-	12-May	Excellent
560			2	Advance Study gate steel tank	-	Added	0	-	12-May	Excellent
561			3	main tank sumerhill bazar	-	Added	0	-	12-May	Excellent
562			4	main tank advance studies below summerhill	-	Added	0	-	12-May	Excellent
563			5	main tank Gangh ram meshphir residence summerhill	-	Added	0	-	12-May	Excellent
564			6	sanjauli inlet guma(inlet)	-	Added	0	-	12-May	Excellent
565			7	sanjauli inlet giri(inlet)	-	Added	0	-	12-May	Excellent
566			8	main tank reserrior sanjauli	-	Added	0	-	12-May	Excellent
567	11-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added				In Process
568			2	main tank kasumpti	-	Added				In Process
569			3	main tank sakrala parimahal	-	Added				In Process
570			4	main tank knologe wood nigam bihar	-	Added				In Process
571			5	main tank means field chotta shimla	-	Added				In Process

572			6	sanjauli inlet guma(inlet)	-	Added	In Process
573	12-May	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	Main tank Kamana Devi Mandir	-	Added	In Process
574			2	main tank kali mandir power house above	-	Added	In Process
575			3	main tank yadgar tutu	-	Added	In Process
576			4	Ridge main tank	-	Added	In Process
577			5	sanjauli inlet guma(inlet)	-	Added	In Process
578			6	sanjauli inlet giri(inlet)	-	Added	In Process
579			7	main tank reserrior sanjauli	-	Added	In Process