

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
567	11-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	0	-	13-May	Excellent
568			2	main tank kasumpti	-	Added	0	-	13-May	Excellent
569			3	main tank sakrala parimahal	-	Added	0	-	13-May	Excellent
570			4	main tank knologe wood nigam bihar	-	Added	0	-	13-May	Excellent
571			5	main tank means field chotta shimla	-	Added	0	-	13-May	Excellent
572			6	sanjauli inlet guma(inlet)	-	Added	0	-	13-May	Excellent
573	12-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank Kamana Devi Mandir	-	Added	In Process			
574			2	main tank kali mandir power house above	-	Added	In Process			
575			3	main tank yadgar tutu	-	Added	In Process			
576			4	Ridge main tank	-	Added	In Process			
577			5	sanjauli inlet guma(inlet)	-	Added	In Process			
578			6	sanjauli inlet giri(inlet)	-	Added	In Process			
579			7	main tank reservior sanjauli	-	Added	In Process			
580	13-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	In Process			

581			2	main tank sec I new shimla	-	Added	In Process
582			3	main tank sec IV New shimla	-	Added	In Process
583			4	main tank sec II New shimla	-	Added	In Process
584			5	main tank kasumpti	-	Added	In Process
585			6	sanjauli inlet guma(inlet)	-	Added	In Process
586			7	sanjauli inlet giri(inlet)	-	Added	In Process
587			8	main tank reservior sanjauli	-	Added	In Process