

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
573	12-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank Kamana Devi Mandir	-	Added	35	-	13-May	unsatisfactory
574			2	main tank kali mandir power house above	-	Added	0	-	13-May	Excellent
575			3	main tank yadgar tutu	-	Added	0	-	13-May	Excellent
576			4	Ridge main tank	-	Added	0	-	13-May	Excellent
577			5	sanjauli inlet guma(inlet)	-	Added	0	-	13-May	Excellent
578			6	sanjauli inlet giri(inlet)	-	Added	0	-	13-May	Excellent
579			7	main tank reservior sanjauli	-	Added	0	-	13-May	Excellent
580	13-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	In Process			
581			2	main tank sec I new shimla	-	Added	In Process			
582			3	main tank sec IV New shimla	-	Added	In Process			
583			4	main tank sec II New shimla	-	Added	In Process			
584			5	main tank kasumpti	-	Added	In Process			
585			6	sanjauli inlet guma(inlet)	-	Added	In Process			
586			7	sanjauli inlet giri(inlet)	-	Added	In Process			

587			8	main tank reservior sanjauli	-	Added	In Process
588	14-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	public tank thana baluganj	-	Added	In Process
589			2	public tap mainline UCO bank in front of chakkar	-	Added	In Process
590			3	main tank sandel chakkar	-	Added	In Process
591			4	public tap ramweshar vaid build new tutu	-	Added	In Process
592			5	public tap behehara bhawan airpot road dower tutu	-	Added	In Process
593			6	main tank reservior sanjauli	-	Added	In Process