Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
608	18-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kamana devi mandir	-	Added	0	-	20-May	Excellent
609			2	main tank steel baluganj chowk	-	Added	0	-	20-May	Excellent
610			3	public tap anadale mandir kainthu	-	Added	0	-	20-May	Excellent
611			4	public tap dhobi ght kainthu	-	Added	0	-	20-May	Excellent
612			5	main tank tara hall upper kainthu	-	Added	0	-	20-May	Excellent
613			6	main tank reservior sanjauli	-	Added	0	-	20-May	Excellent
614			7	WTP ashwani khud	-	Added	0	-	20-May	Excellent
615	19-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank shivpuri Kanlog	-	Added	0	-	21-May	Excellent
616			2	main tank Tara Mandir BCS new shimla	-	Added	0	-	21-May	Excellent
617			3	main tank sec 3 New shimla	-	Added	0	-	21-May	Excellent
618			4	main tank sec4 new shimla	-	Added	0	-	21-May	Excellent
619			5	main tank vikas nagar	-	Added	0	-	21-May	Excellent
620			6	main tank Kasumpti	-	Added	0	-	21-May	Excellent
621			7	main tank sanjauli (outlet)	-	Added	0	-	21-May	Excellent
622	20-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank ridge outlet shiv mandir	-	Added	0	-	22-May	Excellent
623			2	manhar cottage public tap private kuppta dhar	-	Added	0	_	22-May	Excellent
624			3	public tap bharaj bazar	-	Added	0	-	22-May	Excellent
625			4	guma line inlet sanjauli	-	Added	0	-	22-May	Excellent

626			5	giri line inlet sanjauli	-	Added	0	-	22-May	Excellent
627			6	main tank sanjauli reserviou outlet	-	Added	0	-	22-May	Excellent
628	21-May	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	public tap brocast chotta shimla	-	Added			In Process	
629			2	main tank kasumpti	-	Added			In Process	
630			3	shri hari mandir vikas nagar		Added			In Process	
631			4	main tank phase III kamnadhar new shimla	1	Added			In Process	
632			5	main tank phase III police chowki new shimla	1	Added			In Process	
633			6	sanjauli reservior outlet	1	Added			In Process	
	22-May		NO SAMF	PE RECEIVED						


			_	

			_	

			_	

			_	

_			_	

_			_	

_			_	

_			_	

			_	

			_	

			_	

			_	

			_	

			_	

_			_	

_			_	

_			_	