Water samples tested in Department of Microbiology IGMC,Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
634	23-May	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	main tank nabha ground	-	Added	0	-	25-May	Excellent
635			2	main tank sanskkriti colllage fagli	-	Added	In Process			
636			3	public tap bangala colony	-	Added	0	-	25-May	Excellent
637			4	public tap mehta building engine ghar	-	Added	0	-	25-May	Excellent
638			5	main tank north oak underground	-	Added	0	-	25-May	Excellent
639			6	main tank north oak upper head	-	Added	0	-	25-May	Excellent
640			7	public tao purani police chowki sanjauli bazar	-	Added	0	-	25-May	Excellent
641	24-May	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	main tank kasumpti	-	Added	In Process			
642		Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	2	public tap laxmi narayan mandirkasumpti	-	Added	In Process			
643			3	main tank woodvilla hotel side mains field tank no1	-	Added	In Process			
644			4	main tank raj bhawan side main field tank no 2	-	Added	In Process			
645			5	main tank reservior sanjauli	-	Added	In Process			

646			6	sanjauli inlet guma(inlet)	-	Added	In Process
647			7	sanjauli inlet giri(inlet)	-	Added	In Process
648	25-May	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	summerhill road below adwans study main tank	-	Added	In Process
649			2	tap water summerhill chowk	-	Added	In Process
650			3	public tap summer hill bazar	-	Added	In Process
651			4	maun tank summer hill bazar	-	Added	In Process
652			5	reservior sanjauli outlet	-	Added	In Process
653			6	sanjauli inlet guma(inlet)	-	Added	In Process
654			7	sanjauli inlet giri(inlet)	-	Added	In Process