

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
655	26-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kasumpti	-	Added	0	-	28-May	Excellent
656			2	main tank rani ground basant vihar	-	Added	0	-	28-May	Excellent
657			3	public tap lower panthaghati near bhatiya niwas	-	Added	0	-	28-May	Excellent
658			4	main tank underground IAS colony sargin no1	-	Added	0	-	28-May	Excellent
659			5	main tank IAS colony sargin no 2	-	Added	0	-	28-May	Excellent
660			6	reservior sanjauli outlet	-	Added	0	-	28-May	Excellent
661			7	sanjauli inlet guma(inlet)	-	Added	0	-	28-May	Excellent
662	27-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kasumpti	-	Added	In Process			
663			2	main tank phase III near block 6,7 kagna dhar	-	Added	In Process			
664			3	shiv mandir bouri sector 5 phase III kagna dhar	-	Added	In Process			
665			4	Sh Beli Ram Aman Kanj (kitchen) phASE iii scctor56 kagna dhar	-	Added	In Process			

666			5	Sh Ashok Sharma sharma niwas( kitchen) sector 5 phase III kagna dhar	-	Added	In Process
667			6	Smt shasho sani set no II (Kitchen )block no 20 sector 5 kagna dhar	-	Added	In Process
668			7	Sh Kamal Arora (Tanki) sectro 6 block no 5 phase III BCS	-	Added	In Process
669			8	reservior sanjauli outlet	-	Added	In Process
670	28-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kalyani heli pad chharabra	-	Added	In Process
671			2	retret kitchen chharabra	-	Added	In Process
672			3	public tap UCO bank dhalli	-	Added	In Process
673			4	sanjauli inlet guma(inlet)	-	Added	In Process
674			5	giri line inlet sanjauli	-	Added	In Process
675			6	reservior sanjauli outlet	-	Added	In Process