

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
662	27-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kasumpti	-	Added	0	-	29-May	Excellent
663			2	main tank phase III near block 6,7 kagna dhar	-	Added	0	-	29-May	Excellent
664			3	shiv mandir bouri sector 5 phase III kagna dhar	-	Added	180	-	29-May	unsatisfactory
665			4	Sh Beli Ram Aman Kanj (kitchen) phASE iii scctor 56 kagna dhar	-	Added	0	-	29-May	Excellent
666			5	Sh Ashok Sharma sharma niwas (kitchen) sector 5 phase III kagna dhar	-	Added	0	-	29-May	Excellent
667			6	Smt shasho sani set no II (Kitchen)block no 20 sector 5 kagna dhar	-	Added	0	-	29-May	Excellent
668			7	Sh Kamal Arora (Tanki) sectro 6 block no 5 phase III BCS	-	Added	180	-	29-May	unsatisfactory
669			8	reservior sanjauli outlet	-	Added	0	-	29-May	Excellent
670	28-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kalyani heli pad chharabra	-	Added	In Process			
671			2	retret kitchen chharabra	-	Added	In Process			

672			3	public tap UCO bank dhalli	-	Added	In Process
673			4	sanjauli inlet guma(inlet)	-	Added	In Process
674			5	giri line inlet sanjauli	-	Added	In Process
675			6	reservior sanjauli outlet	-	Added	In Process
675	29-May	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	main tank phase III near police chowki new shimla	-	Added	In Process
677			2	main tank phase III block 6,7 Kagna Dhar	-	Added	In Process
678			3	main tank kalyani heli pad chharabra	-	Added	In Process
679			4	retreat (kitchen)	-	Added	In Process
680			5	sanjauli inlet guma(inlet)	-	Added	In Process
681			6	giri line inlet sanjauli	-	Added	In Process
682			7	reservior sanjauli outlet	-	Added	In Process
683			8	main tank fagli near sanskrit collage	-	Added	In Process