

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
670	28-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kalyani heli pad chharabra	-	Added	0	-	30-May	Excellent
671			2	retret kitchen chharabra	-	Added	0	-	30-May	Excellent
672			3	public tap UCO bank dhalli	-	Added	0	-	30-May	Excellent
673			4	sanjauli inlet guma(inlet)	-	Added	0	-	30-May	Excellent
674			5	giri line inlet sanjauli	-	Added	0	-	30-May	Excellent
675			6	reservior sanjauli outlet	-	Added	0	-	30-May	Excellent
675	29-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank phase III near police chowki new shimla	-	Added	In Process			
677			2	main tank phase III block 6,7 Kagna Dhar	-	Added	In Process			
678			3	main tank kalyani heli pad chharabra	-	Added	In Process			
679			4	retreat (kitchen)	-	Added	In Process			
680			5	sanjauli inlet guma(inlet)	-	Added	In Process			
681			6	giri line inlet sanjauli	-	Added	In Process			

682			7	reservior sanjauli outlet	-	Added	In Process
683			8	main tank fagli near sanskrit collage	-	Added	In Process
684	29-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kasumpti	-	Added	In Process
685			2	main tank kalyani heli pad chharabra	-	Added	In Process
686			3	retreat (kitchen)	-	Added	In Process
687			4	pump house mashobra	-	Added	In Process
688			5	sanjauli inlet guma(inlet)	-	Added	In Process
689			6	giri line inlet sanjauli	-	Added	In Process
690			7	reservior sanjauli outlet	-	Added	In Process