

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
675	29-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank phase III near police chowki new shimla	-	Added	0	-	31-May	Excellent
677			2	main tank phase III block 6,7 Kagna Dhar	-	Added	0	-	31-May	Excellent
678			3	main tank kalyani heli pad chharabra	-	Added	0	-	31-May	Excellent
679			4	retreat (kitchen)	-	Added	0	-	31-May	Excellent
680			5	sanjauli inlet guma(inlet)	-	Added	0	-	31-May	Excellent
681			6	giri line inlet sanjauli	-	Added	180	-	31-May	unsatisfactory
682			7	reservior sanjauli outlet	-	Added	180	-	31-May	unsatisfactory
683			8	main tank fagli near sanskrit collage	-	Added	0	-	31-May	Excellent
684	29-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kasumpti	-	Added	In Process			
685			2	main tank kalyani heli pad chharabra	-	Added	In Process			
686			3	retreat (kitchen)	-	Added	In Process			
687			4	pump house mashobra	-	Added	In Process			
688			5	sanjauli inlet guma(inlet)	-	Added	In Process			

689			6	giri line inlet sanjauli	-	Added	In Process
690			7	reservior sanjauli outlet	-	Added	In Process
691	25-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank ridge outlet shiv mandir	-	Added	In Process
692			2	public tap near pump house lakkar bazar	-	Added	In Process
693			3	main tank kalyani heli pad chharabra	-	Added	In Process
694			4	retreat (kitchen)	-	Added	In Process
695			5	sanjauli inlet guma(inlet)	-	Added	In Process
696			6	giri line inlet sanjauli	-	Added	In Process
697			7	giri line inlet sanjauli	-	Added	In Process