

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
698	1-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	kamal Arora set 6 block no 5	-	Added	0	-	03-Jun	Excellent
699			2	Kasumpti reservoir	-	Added	0	-	03-Jun	Excellent
700			3	kalyani tank	-	Added	0	-	03-Jun	Excellent
701			4	retreat (kitchen)	-	Added	0	-	03-Jun	Excellent
702			5	sanjauli inlet guma (inlet)	-	Added	0	-	03-Jun	Excellent
703			6	giri line inlet sanjauli	-	Added	0	-	03-Jun	Excellent
704			7	reservoir sanjauli outlet	-	Added	0	-	03-Jun	Excellent
705		samples received from office of block medical officer chirgaon distt shimla	8	CHC chrgaon PHC diudi Sub Centre janglikh Village Janglikh Tap water 1	-	Added				In Process
706			9	CHC chrgaon PHC diudi Sub Centre janglikh Village Janglikh Tap water 2	-	Added				In Process
707	2-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Mains field out let	-	Added				In Process
708			2	Kasumpti reservoir	-	Added				In Process
709			3	kalyani tank	-	Added				In Process
710			4	jaungla tank	-	Added				In Process

711			5	retreat (kitchen)	-	Added	In Process
712			6	sanjauli inlet gumma	-	Added	In Process
713			7	sanjauli inlet giri	-	Added	In Process
714			8	sanjauli reservior outlet	-	Added	In Process
715	3-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	retreat (kitchen)	-	Added	In Process
716			2	jaungla tank	-	Added	In Process
717			3	kalyani tank	-	Added	In Process
718			4	craigneno tank	-	Added	In Process
719			5	reservior sanjauli outlet	-	Added	In Process
720			6	sanjauli inlet guma(inlet)	-	Added	In Process
721			7	giri line inlet sanjauli	-	Added	In Process
722			8	Kasumpti reservior	-	Added	In Process