

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
763	9-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	lower khalini public tap	-	Added	0	-	11-Jun	Excellent
764			2	set. No 36 below pine resident tap water	-	Added	0	-	11-Jun	Excellent
765			3	set. No 36 below pine resident aquagard	-	Added	0	-	11-Jun	Excellent
766			4	set No below pine residence	-	Added	0	-	11-Jun	Excellent
767			5	kasumpti reservoir	-	Added	0	-	11-Jun	Excellent
768			6	kasumpti near mandir public tap	-	Added	0	-	11-Jun	Excellent
769			7	sanjauli reservoir out let	-	Added	0	-	11-Jun	Excellent
770	10-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	idhan sabha chowk public ta	-	Added				In Process
771			2	M C office chaura maidan Ta	-	Added				In Process
772			3	103 Tank (S)	-	Added				In Process
773			4	103 Tank (B)	-	Added				In Process
774			5	railway statin public Tap	-	Added				In Process

775			6	kasumpti resrvior	-	Added	In Process
776			7	sanjauli reservoir out let	-	Added	In Process
777	10-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	block host tap water	-	Added	In Process
778			2	kasumpti reserrior	-	Added	In Process
779			3	SDA complex tank	-	Added	In Process
780			4	bangala colony public tap	-	Added	In Process
781			5	engine ghar parking public tap	-	Added	In Process
782			6	sanjauli reserrior out let	-	Added	In Process