

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1010	17-Jul	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Lakkar Bazaar Public Tap	-	Added	0		19-Jul	Excellent
1011			2	Snow Down pump house	-	Added	0			Excellent
1012			3	Priory House Near Snowdown Pump House Public tap	-	Added	0			Excellent
1013			4	Sanjauli Reservoir outlet	-	Added	0			Excellent
1014			5	Enginee Ghar Tank	-	Added	25			Unsatisfactory
1015			6	bangala colony public tap	-	Added	0			Excellent
1016			7	Kasumpti Reservoir	-	Added	13			Unsatisfactory
1017			8	Raj Bir Auto Borwall	-	Not Added	13			Unsatisfactory
1018	18-Jul	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Sanjauli Reservoir outlet	-	Added				In Process
1019			2	Sanjauli inlet Giri	-	Added				In Process
1020			3	Kasumpti Reservoir	-	Added				In Process

1021			4	H.P.P.W.D Kasumpti Tank	-	Added	In Process
1022			5	Water ATM Ridge	-	Added	In Process
1023			6	M.C Office Chaura maidan supply tap water	-	Added	In Process
1024			7	I.I.A.S Staff Tank	-	Added	In Process
1025			8	Bailuganj Police Station Public Tap	-	Added	In Process
1026	19-Jul	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Near Police line Bharari public tap	-	Added	In Process
1027			2	Sanjauli reservoir outlet	-	Added	In Process
1028			3	Sanjauli inlet Guma	-	Added	In Process
1029			4	Laxmi Narayan Mandir Kasumpti public tap	-	Added	In Process
1030			5	Kasumpti reservoir	-	Added	In Process
1031			6	Hotel Mahamaya source	-	Not Added	In Process