

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1018	18-Jul	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Sanjauli Reservoir outlet	-	Added	0	-	20-Jul	Excellent
1019			2	Sanjauli inlet Giri	-	Added	0	-		Excellent
1020			3	Kasumpti Reservoir	-	Added	0	-		Excellent
1021			4	H.P.P.W.D Kasumpti Tank	-	Added	0	-		Excellent
1022			5	Water ATM Ridge	-	Added	0	-		Excellent
1023			6	M.C Office Chaura maidan supply tap water	-	Added	180+	-		Unsatisfactory
1024			7	I.I.A.S Staff Tank	-	Added	13	-		Unsatisfactory
1025			8	Bailuganj Police Station Public Tap	-	Added	0	-		Excellent
1026	19-Jul	Samples received from Corporate Health Officer, Municipal Corporation	1	Near Police line Bharari public tap	-	Added	In Process			
1027			2	Sanjauli reservoir outlet	-	Added	In Process			
1028			3	Sanjauli inlet Guma	-	Added	In Process			