

| Water samples tested in Department of Microbiology IGMC, Shimla | | | | | | | | | | |
|---|--------|---|--------------|-----------------------------------|------|-----------------|------------|-----|-------------|----------------|
| Lab Sr. no. | Date | Received through Email/Phone No. | Daily Sr No. | Source | Site | Na thiosulphate | PCC | DCC | Reported on | Result |
| 896 | 29-Jun | Samples received from Corporate Health Officer, Municipal | 1 | near C.PRI public tap | - | Added | 0 | - | 1-Jul | Excellent |
| 897 | | | 2 | shiv puri tank | - | Added | 0 | - | 1-Jul | Excellent |
| 898 | | | 3 | kashwiri niwas public tap kanlog | - | Added | 0 | - | 1-Jul | Excellent |
| 899 | | | 4 | knollswood tank | - | Added | 12 | - | 1-Jul | unsatisfactory |
| 900 | | | 5 | kasumpti reservoir | - | Added | 11 | - | 1-Jul | unsatisfactory |
| 901 | | | 6 | sanjauli reservoir out let | - | Added | 12 | - | 1-Jul | unsatisfactory |
| 902 | 30-Jun | Samples received from Corporate Health Officer, Municipal | 1 | chuura maidan MC office tap water | - | Added | In Process | | | |
| 903 | | | 2 | HAS stell tank | - | Added | In Process | | | |
| 904 | | | 3 | near GR mushaheir tank | - | Added | In Process | | | |
| 905 | | | 4 | bailuganj police station pub | - | Added | In Process | | | |
| 906 | | | 5 | kasumpti reservoir | - | Added | In Process | | | |
| 907 | | | 6 | sanjauli reservoir out let | - | Added | In Process | | | |
| 908 | 1-Jul | | 1 | satsang lakkar bazar | - | Added | In Process | | | |

| | | | | | | | |
|-----|--|--|---|--|---|-------|------------|
| 909 | | | 2 | bhagra niwas public tap | - | Added | In Process |
| 910 | | | 3 | KN hospital public tap | - | Added | In Process |
| 911 | | | 4 | phase III near police chowki BCS tank | - | Added | In Process |
| 912 | | | 5 | kasumpti reserrior | - | Added | In Process |
| 913 | | | 6 | sanjauli reservoir out let | - | Added | In Process |

