

Water samples tested in Department of Microbiology IGMC, Shimla since 1st Jan 2016										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1126	4-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Mainsfield Tank No1		Added	0	-	06-Aug	Excellent
1127			2	Main Tank Means Field No-2		Added	0	-		Excellent
1128			3	Raj Bhavan Kitchen		Added	0	-		Excellent
1129			4	Main Tank Secteriate Raj Bhavan		Added	25	-		Unsatisfactory
1130			5	Main tank kasumpti		Added	0	-		Excellent
1131			6	Giri inlet sanjauli reservior		Added	0	-		Excellent
1132			7	Guma inlet Sanjauli Reservior		Added	0	-		Excellent
1133	5-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main Tank Sector-2 New Shimla		Added				Excellent
1134			2	Main Tank Sector-3 New Shimla		Added				Excellent
1135			3	Main tank kasumpti		Added				Excellent
1136			4	Public Tap Laxmi narayan mandir kasumpti		Added				Excellent
1137			5	Public Tap Kasumpti Chowk		Added				Excellent
1138			6	Sanjauli Reservoir Outlet		Added				Excellent
1139			7	Guma inlet Sanjauli Reservior		Added				Excellent
1140			8	Giri inlet sanjauli reservior		Added				Excellent

1141	6-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Public Tap lower chakkar	Added				Excellent
1142			2	main tank sandel chakkar	Added				Excellent
1143			3	Main tank Kamna devi Mandir	Added				Excellent
1144			4	main tank kasumpti	Added				Excellent
1145			5	Guma inlet Sanjauli reservoir	Added				Excellent
1146			6	Sanjauli reservoir outlet	Added				Excellent
1147			7	Forest office Talland near Natural Chasma	Nil	180+	-		Unsatisfactory