

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1133	5-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main Tank Sector-2 New Shimla		Added	0			Excellent
1134			2	Main Tank Sector-3 New Shimla		Added	0			Excellent
1135			3	Main tank kasumpti		Added	0			Excellent
1136			4	Public Tap Laxmi narayan mandir kasumpti		Added	0			Excellent
1137			5	Public Tap Kasumpti Chowk		Added	0			Excellent
1138			6	Sanjauli Reservoir Outlet		Added	0			Excellent
1139			7	Guma inlet Sanjauli Reservoir		Added	0			Excellent
1140			8	Giri inlet sanjauli reservoir		Added	0			Excellent
1141	6-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public Tap lower chakkar		Added	0			Excellent
1142			2	main tank sandel chakkar		Added	0			Excellent
1143			3	Main tank Kamna devi Mandir		Added	0			Excellent
1144			4	main tank kasumpti		Added	0			Excellent
1145			5	Guma inlet Sanjauli reservoir		Added	0			Excellent
1146			6	Sanjauli reservoir outlet		Added	0			Excellent
1147			7	Forest office Talland near Natural Chasma		Nil	180+	-		Unsatisfactory
1148	7-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	M.C office Chorra Maiden		Added				Excellent

1149			2	Main tank advance studies Jangel(Summer hill)		Added				Excellent
1150			3	Main tank STEel advance studies Gate		Added				Excellent
1151			4	Main tank kasumpti		Added				Excellent
1152			5	Sanjauli Reservior		Added				Excellent
1153			6	Guma inlet Sanjauli reservior		Added				Excellent
1154			7	Giri inlet sanjauli reservior		Added				Excellent
1155	8-Ausust	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public Tap Khalini Chowk		Added				Excellent
1156			2	Public Tap Hanuman Mandir Road Lower Khalini		Added				Excellent
1157			3	Public Tap Laxmi Narayan Mandir Vikas Nagar		Added				Excellent
1158			4	Main Tank Kasumpti		Added				Excellent
1159			5	Sanjauli Reservior Outlet		Added				Excellent
1160			6	Sanjauli Reservoir Inlet Gumma		Added				Excellent
1161			7	Sanjauli Reservoir Inlet Giri		Added				Excellent
1162	9-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank kasumpti	-	Added	0	-	11-Aug	Excellent
1163			2	main tank sect raj bhawan	-	Added	0	-		Excellent
1164			3	Main tank upper jakhu	-	Added	0	-		Excellent
1165			4	Main tank(u.g) jakhu	-	Added	0	-		Excellent
1166			5	Gumma Inlet	-	Added	0	-		Excellent
1167			6	Giri inlet	-	Added	0	-		Excellent

1168	10-Augus	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	public tap bharari bazar	-	Added	0		12-Aug	Excellent
1169			2	Public Tap Police Line Bhavan	-	Added	0			Excellent
1170			3	Main Tank Kalisten Outlet	-	Added	0			Excellent
1171			4	Main tank bharari	-	Added	0			Excellent
1172			5	Main tank Kasumpti	-	Added	0			Excellent
1173			6	Sanjauli Reservoir Gumma Inlet	-	Added	0			Excellent
1174			7	Sanjauli Reservoir Giri Inlet	-	Added	0	-		Excellent
1175	11-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tankbadha 103	-	Added	1		13-Aug	Satisfactory
1176			2	sanjauli reserrior outlet	-	Added	0			Excellent
1178			3	main tank sakrala primehal	-	Added	0			Excellent
1179			4	main tank kasumpti	-	Added	0			Excellent
1180			5	Gumma Inlet	-	Added	0			Excellent
1181			6	Giri inlet	-	Added	0			Excellent
1182	12-Aug	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank knologe wood	-	Added	0			Excellent
1183			2	main tank kasumpti	-	Added	0			Excellent
1184			3	main tank SDA complex	-	Added	0			Excellent
1185			4	reserrior sanjauli outlet	-	Added	0			Excellent
1186			5	Gumma Inlet	-	Added	0			Excellent
1187			6	Giri inlet	-	Added	0			Excellent