

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1341	4-Sep	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Mayor Residence Sargin (Kitchen)		Added	0	–	6-Sep	Excellent
1342			2	Mayor Residence ground floor (Kitchen) Sargin		Added	0	–		Excellent
1343			3	Mayor Residence (Inlet) Sargin		Added	0	–		Excellent
1344			4	Main Tank Kasumpti		Added	0	–		Excellent
1345			5	Guma inlet Sanjauli Reservoir		Added	0	–		Excellent
1346			6	Giri Inlet Reservoir Sanjauli		Added	0	–		Excellent
1347	5 Sept	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Main Tank Ridge Outlet Shiv Mandir Middle Bazar		Added	0	–	7-Sep	Excellent
1348			2	Public Tap Lower Bazar Near Tunnel		Added	0	–		Excellent
1349			3	Public Tap Indira Chowk Lower Bazar		Added	0	–		Excellent
1350			4	Public Tap Cart Road		Added	0	–		Excellent
1351			5	Main Tank Kasumpati		Added	0	–		Excellent
1352			6	Sanjauli Reservoir Outlet		Added	0	–		Excellent
1353			7	Giri Inlet Sanjauli Reservoir		Added	0	–		Excellent
1354			8	Gumma Inlet Sanjauli Reservoir		Added	0	–		Excellent

1362	7-Sep	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank chotta fingas	-	Added	0	-	9-Sep	Excellent
1363			2	Main tank bada fingas	-	Added	0	-		Excellent
1364			3	public tap ram mandir ram bazaar	-	Added	0	-		Excellent
1365			4	Water ATM purana bus stand Shimla	-	Added	0	-		Excellent
1366			5	Main tank Kasumpti	-	Added	0	-		Excellent
1367			6	Sanjauli reservoir outlet	-	Added	0	-		Excellent
1368			7	Guma inlet Sanjauli Reservior	-	Added	0	-		Excellent
1369			8	Giri Inlet Sanjauli Reservoir	-	Added	0	-		Excellent