

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
1370	8-Sep	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank kasumpti	-	Added	0	-		Excellent
1371			2	Main tank dhalli bazaar	-	Added	0	-		Excellent
1372			3	Main tank dhallifilter	-	Added	0	-		Excellent
1373			4	Maintank mashobra	-	Added	0	-		Excellent
1374			5	sanjaulireservoir outlet	-	Added	0	-		Excellent
1375			6	Girisanjaulireservoir inlet	-	Added	0	-		Excellent
1376			7	Gumasanjaulireservoir inlet	-	Added	0	-		Excellent
1377	9-Sep	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank Shivpuri	-	Added	0	-		Excellent
1378			2	public tap jobhi Niwas Shivpuri	-	Added	0	-		Excellent
1379			3	public tap jobhi Kashmiri Bhawan Kanlag	-	Added	180+	-		Unsatisfactory
1380			4	Main tank SDA Complex Kasumpti	-	Added	0	-		Excellent
1381			5	Main tank Kasumpti	-	Added	0	-		Excellent
1382			6	Guma inlet Sanjauli Reservoir	-	Added	0	-		Excellent
1383			7	Giri Inlet Sanjauli Reservoir	-	Added	0	-		Excellent

1384	10-Sep	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap Chota shimla chowk	-	Added	0	-		Excellent
1385			2	Main tank Kasumpti	-	Added	0	-		Excellent
1386			3	Main tank wagala colony Sanjauli	-	Added	0	-		Excellent
1387			4	Main tank engine ghar Sanjauli	-	Added	0	-		Excellent
1388			5	Giri Inlet Sanjauli	-	Added	0	-		Excellent
1389			6	Guma Inlet	-	Added	180	-		Unsatisfactory
1390			7	Main tank North Oak	-	Added	0	-		Excellent