

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3849	20-Oct	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Tap Water Dhingu Mandir	-	added	1	-	22-Oct	satisfactory
3850			2	Dhingu Mandir Tank (Upper) Outlet	-	added	0	-		Excellent
3851			3	Dhingu Mandir Tank(Lower)	-	added	0	-		Excellent
3852			4	Public Tap Goel Apartment Dhingu (Left)	-	added	0	-		Excellent
3853			5	Public Tap Goel Apartment Dhingu (Right)	-	added	0	-		Excellent
3854			6	Public Tap Laxmi Narain Mandir Sanjauli	-	added	0	-		Excellent
3855			7	sanjauli reservoir outlet	-	added	0	-		Excellent
3856			8	kasumpti reservoir	-	added	0	-		Excellent
3857	21-Oct	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Tap water block 36/2 Nabha	-	added	0	-	23-Oct	Excellent
3858			2	Nabha Supply	-	added	0	-		Excellent
3859			3	Phagli Tank	-	added	0	-		Excellent
3860			4	Tap water Keyman's Residence Phagli	-	added	3	-		Satisfactory
3861			5	kasumpti reservoir	-	added	0	-		Excellent
3862			6	sanjauli reservoir outlet	-	added	0	-		Excellent