

| Water samples tested in Department of Microbiology IGMC, Shimla | | | | | | | | | | |
|---|--------|---|--------------|-------------------------------------|------|-----------------|------|-----|-------------|----------------|
| Lab Sr. no. | Date | Received through Email/Phone No. | Daily Sr No. | Source | Site | Na thiosulphate | PCC | DCC | Reported on | Result |
| 4020 | 14-Nov | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Public tap vidhaan sabha chowk | - | added | 0 | - | 16-Nov | Excellent |
| 4021 | | | 2 | Tap water MC quarters chura | - | added | 0 | - | 16-Nov | Excellent |
| 4022 | | | 3 | Sanjauli reservoir outlet | - | added | 0 | - | 16-Nov | Excellent |
| 4023 | | | 4 | Kasumpti reservoir | - | added | 0 | - | 16-Nov | Excellent |
| 4024 | | | 5 | Natural source raziana new II | - | added | 11 | - | 17-Nov | unsatisfactory |
| 4025 | | | | Natural source raziana new one | - | added | 180+ | - | 16-Nov | unsatisfactory |
| 4026 | 15-Nov | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Kasumpti reservoir | - | added | 0 | - | 17-Nov | Excellent |
| 4027 | | | 2 | Kasumpti SDA Complex Tank | - | added | 0 | - | 17-Nov | Excellent |
| 4028 | | | 3 | Public Tap Below Axis Bank SDA | - | added | 0 | - | 17-Nov | Excellent |
| 4029 | | | 4 | Vikas Nagar -41 Tank | - | added | 0 | - | 17-Nov | Excellent |
| 4030 | | | 5 | Public Tap Shanti Niwas Vikas Nagar | - | added | 0 | - | 17-Nov | Excellent |
| 4031 | | | 6 | Public Tap Vikas Nagar Mandir | - | added | 0 | - | 17-Nov | Excellent |
| 4032 | | | 7 | Sanjauli reservoir outlet | - | added | 0 | - | 17-Nov | Excellent |