

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3036	12-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	public tap police line khaithu	-	added	0	-	14-Jun	Excellent
3037			2	public tap krishna hill anadel kaithu	-	added	0	-		Excellent
3038			3	public tap gov. school anadel kaithu	-	added	0	-		Excellent
3039			4	public tap anadel chowk kaithu	-	added	0	-		Excellent
3040			5	main tank kasumpti	-	added	0	-		Excellent
3041			6	sanjauli resrvior outlet	-	added	0	-		Excellent
3042	13-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank ridge outlet shiv mandir middle bazar	-	added	0	-		Excellent
3043			2	public tap gali no. 5 middle bazar	-	added	0	-		Excellent
3044			3	public tap near tunnel lower bazar	-	added	0	-		Excellent
3045			4	public tap indiira chowk lower bazar	-	added	0	-		Excellent
3046			5	main tank kasumpti	-	added	0	-		Excellent
3047			6	Gumma inlet sanjauliv reservior	-	added	0	-		Excellent
3048	14-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank nowdgewood outlet chotta shimla	-	added	0	-	16-Jun	Excellent
3049			2	Public Tap Khalini Chowk	-	added	0	-		Excellent
3050			3	Public Tap Hanuman Mandir Road Lower	-	added	0	-		Excellent
3051			4	main supply bypass chowk khalini	-	added	0	-		Excellent
3052			5	main tank kasumpti	-	added	0	-		Excellent
3053			6	sanjauli resrvior outlet	-	added	0	-		Excellent
3054	15-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap Lower Panthaghati near Laxminarayan Mandir	-	added	1		17-Jun	satisfactory
3055			2	Main tank IS colony Sergeant	-	added	0	-		Excellent
3056			3	Main supply Om Niwas Sergeant	-	added	0	-		Excellent
3057			4	main supply tharun villa upper	-	added	0	-		Excellent
3058			5	Main Tank Kasumpati	-	added	0	-		Excellent
3059			6	Sanjauli Reservoir Outlet	-	added	0	-		Excellent
3060	16-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap near CPRI Bamloi	-	added	0	-	18-Jun	Excellent
3061			2	Main tank Shiv Puri	-	added	0	-		Excellent
3062			3	Main supply Sharma Niwas Kamlog	-	added	0	-		Excellent

3063			4	Main tank Kasumpti	-	added	0	-		Excellent
3064			5	Sanjauli Reservoir (Outlet)	-	added	0	-		Excellent
3065			6	Sanjauli Reservoir Giri Inlet	-	added	0	-		Excellent
3066	17-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	public tap c.t.o	-	added	0	-	19-Jun	Excellent
3067			2	public tap ram mandir ram bazar	-	added	0	-		Excellent
3068			3	public tap DDU hospital	-	added	0	-		Excellent
3069			4	water ATM old bus stand	-	added	0	-		Excellent
3070			5	public tap cart road	-	added	0	-		Excellent
3071			6	main tank kasumpti	-	added	0	-		Excellent
3072			7	sanjauli reservoir outlet	-	added	0	-		Excellent