

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulph ate	PCC	DCC	Reported on	Result
3178	5-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	public tap lakkar bazar	-	added	0	-	7-Jul	Excellent
3179			2	public tap police chowki lakkar bazar	-	added	0	-		Excellent
3180			3	public tap near snow down pump house	-	added	1	-		Satisfactory
3181			4	snow down pump house	-	added	0	-		Excellent
3182			5	IGMC public tap	-	added	0	-		Excellent
3183			6	sanjauli resevior outlet	-	added	0	-		Excellent
3184			7	kasumpti reserrior	-	added	0	-		Excellent
3185	6-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Advance Study Tank	-	added				Excellent
3186			2	I.I.AS Steel Tank	-	added				Excellent
3187			3	Summer Hill Bazaar Tank	-	added				Excellent
3188			4	public tap lower summer hill bazar	-	added				Excellent
3189			5	G.R. Musshafari Tank Boileauganj	-	added				Excellent
3190			6	Kasumpti Reservoir	-	added				Excellent
3191			7	Sanjauli Reservoir Outlet	-	added				Excellent
3192	7-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Sanjauli Reservoir Outlet	-	added			09-Jul	in process
3193			2	Kasumpti Reservoir	-	added				in process
3194			3	Rajvir Motors Bypass Road Borwell	-	added	180+			unsatisfactory
3195			4	Rhaghav Sood Borwell Bypass Road	-	added				in process
3196			5	Hote Pine View Borwell No I	-	added	3			satisfactory
3197			6	Hote Pine View Borwell No II	-	added	90			unsatisfactory