

| Water samples tested in Department of Microbiology IGMC, Shimla | | | | | | | | | | |
|---|--------|---|--------------|---------------------------------|------|-----------------|-----|-----|-------------|----------------|
| Lab Sr. no. | Date | Received through Email/Phone No. | Daily Sr No. | Source | Site | Na thiosulphate | PCC | DCC | Reported on | Result |
| 3211 | 10-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Kamla Nehru Hospital Public Tap | - | added | 0 | - | 12-Jul | Excellent |
| 3212 | | | 2 | New Shimla Sec-4 Tank | - | added | 0 | - | | Excellent |
| 3213 | | | 3 | New Shimla Sec-2 Tank | - | added | 0 | - | | Excellent |
| 3214 | | | 4 | New Shimla Sec-1 Tank | - | added | 0 | - | | Excellent |
| 3215 | | | 5 | Kasumpti Reservoir | - | added | 0 | - | | Excellent |
| 3216 | | | 6 | Sanjauli Reservoir Outlet | - | added | 0 | - | | Excellent |
| 3217 | 11-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Kasumpti Reservoir | - | added | | | | in process |
| 3218 | | | 2 | IAS colony sargheen tank | - | added | 3 | | | satisfactory |
| 3219 | | | 3 | supply om bhawan sargheen | - | added | | | | in process |
| 3220 | | | 4 | public tap lower panthaghati | - | added | | | | in process |
| 3221 | | | 5 | supply Tarun villa panthaghati | - | added | 11 | | | unsatisfactory |
| 3222 | | | 6 | Sanjauli Reservoir Outlet | - | added | | | | in process |