

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3229			7	Sanjauli Reservoir Outlet	-	added	0	-		Excellent
3230	13-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank knowlge wood	-	added	0	-	15-Jul	Excellent
3231			2	public tap khalenee chowk	-	added	0	-		Excellent
3232			3	Public Tap Hanuman Mandir Road Lower Khalini	-	added	0	-		Excellent
3233			4	main supply satya bhawan bhagwati nagar jangedee	-	added	0	-		Excellent
3234			5	main tank kasumpti	-	added	0	-		Excellent
3235			6	sanjauli reservior outlet	-	added	0	-		Excellent
3236	14-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main Tank Yadghar Tutu	-	added	0	-	16-Jul	Excellent
3237			2	Public Tap Dev Kutir Niwas Lower Tutu	-	added	0	-		Excellent
3238			3	Hand Pump Nalagarh Road Near Shamshan Ghat Tutu	-	added	3	-		satisfactory
3239			4	Main Tank Kali Mata Mandir Tavi Tutu	-	added	0	-		Excellent
3240			5	Main Tank Kasumpti	-	added	0	-		Excellent
3241			6	Sanjauli Reservoir Outlet	-	added	1	-		satisfactory