

**Water samples tested in Department of Microbiology IGMC, Shimla**

Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3273	20-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public Tap Ashrat Meat Shop Eadgha	-	added	0	-	22-Jul	Excellent
3274			2	Public Tap Councillor Niwas Ruldu Bhatta	-	added	0	-	22-Jul	Excellent
3275			3	Main Tank Kasumpati	-	added	0	-	22-Jul	Excellent
3276			4	Over-head Tank Main North Oak Sanjauli	-	added	0	-	22-Jul	Excellent
3277			5	Tank Underground North Oak Sanjauli	-	added	0	-	22-Jul	Excellent
3278			6	Sanjauli Reservoir Outlet	-	added	0	-	22-Jul	Excellent
3279	21-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	water ATM ridge	-	added	0	-	23-Jul	Excellent
3280			2	yatti sood hotel pine view bore well no 2 opposite mela ram sood petrol pump kaithu	-	added	25	-		unsatisfactor
2381			3	water ATM laxmi narayan mandir vikasnagar	-	added	0	-		Excellent
3282			4	public tap laxmi narayan mandir vikasnagar	-	added	0	-		Excellent
3283			5	Main Tank Kasumpati	-	added	0	-		Excellent
3284			6	water ATM old bus stand	-	added	0	-		Excellent
3285			7	Sanjauli Reservoir Outlet	-	added	0	-		Excellent
3286	22-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public Tap Ridge	-	added	1	-	24-Jul	Satisfactory
3287			2	main tank ridge outlet shiv mandir middle bazar	-	added	0	-		Excellent
3288			3	public tap indira chowk lower bazar	-	added	0	-		Excellent

3289			4	Main tank Kasumpti	-	added	0	-		Excellent
3290			5	Giri inlet Sanjauli reservior	-	added	0	-		Excellent
3291			6	sanjauli reservior outlet	-	added	0	-		Excellent