

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3122	26-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kasumpti	-	added	0	-	28-Jun	Excellent
3123			2	main tank noles wood left side chhota shimla	-	added	0	-		Excellent
3124			3	main tank noles wood right side chhota shimla	-	added	0	-		Excellent
3125			4	Raj Bhawan Kitchen	-	added	0	-		Excellent
3126			5	main tank HP sectriate near Raj Bhawan	-	added	0	-		Excellent
3127			6	reservoir sanjauli outlet	-	added	1	-		satisfactory
3128	27-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank chhota fingask	-	added	0	-	29-Jun	Excellent
3129			2	main tank big fingask	-	added	0	-		Excellent
3130			3	main supply jasta niwas fingask	-	added	0	-		Excellent
3131			4	public tap state mark churce building below kali	-	added	0	-		Excellent
3132			5	main tank kasumpti	-	added	0	-		Excellent
3133			6	reservoir sanjauli outlet	-	added	0	-		Excellent
3134	28-Jun	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public Tap Tibiti Colony Nabha	-	added	0	-	1-Jul	Excellent
3135			2	Main supply near shoping complex Nabha	-	added	0	-		Excellent
3136			3	Main thank Phagali	-	added	0	-		Excellent
3137			4	Public Tap Govt School Phagali	-	added	0	-		Excellent
3138			5	Main Tank Kasumpti	-	added	0	-		Excellent
3139			6	Sanjauli Reservoir outlet	-	added	0	-		Excellent