

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
3537	31-Aug	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Main tank kasumpti	-	added	0	-	2-Sep	Excellent
3538			2	Dhingo pump house near tunnel Dhalli	-	added	0	-	2-Sep	Excellent
3539			3	Public Tap Dhalli Bazar	-	added	0	-	2-Sep	Excellent
3540			4	Public tap near UCO Bank Dhalli Bazar	-	added	0	-	2-Sep	Excellent
3541			5	Dhali Filter	-	added	0	-	2-Sep	Excellent
3542			6	Sanjauli Reservoir outlet	-	added	0	-	2-Sep	Excellent
3543	1-Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank sec 1 new shimla	-	added	2		3-Sep	satisfactory
3544			2	main tank sec II new shimla	-	added	0		3-Sep	Excellent
3545			3	main tank sec IV new shimla	-	added	0		3-Sep	Excellent
3546			4	main tank sec III new shimla	-	added	0		3-Sep	Excellent
3547			5	Main tank kasumpti	-	added	0		3-Sep	Excellent
3548			6	Sanjauli Reservoir outlet	-	added	0		3-Sep	Excellent
3549	2-Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap near CPRI Bemloi	-	added	0		4-Sep	Excellent
3550			2	Main tank Kasumpti	-	added	0		4-Sep	Excellent
3551			3	Main tank aupper dingu mandir	-	added	0		4-Sep	Excellent
3552			4	Main tank lower dingu mandir	-	added	0		4-Sep	Excellent
3553			5	Public tap laxmi narayan mandir sanjauli	-	added	0		4-Sep	Excellent