

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	Final report (72Hrs)	Reported on	Result
834	10-May	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Sanjauli Reservoir outlet	-	added	0	-	12-May	Excellent
835			2	Dhali Tunnel Pump House	-	added	0	-	12-May	Excellent
836			3	Housing board colony sanjauli upper tank	-	added	0	-	12-May	Excellent
837			4	Housing board colony sanjauli lower tank	-	added	0	-	12-May	Excellent
838			5	Tap Water central store Maliana	-	added	0	-	12-May	Excellent
839			6	Kasumpti reservoir outlet	-	added	0	-	12-May	Excellent
840	11-May	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Sanjauli Reservoir Outlet	-	added	0	-	13-May	Excellent
841			2	P Tap R.L. Sharma Dhabha Dhali Bazar	-	added	0	-	13-May	Excellent
842			3	P Tap near UCO Bank Dhali Bazar	-	added	0	-	13-May	Excellent
843			4	Dhali Filter	-	added	0	-	13-May	Excellent
844			5	Mashobra tank outlet	-	added	0	-	13-May	Excellent
845			6	P Tap near Kapoor Dhaba Mashobra	-	added	0	-	13-May	Excellent
846			7	Kasumpati Reservoir Outlet	-	added	0	-	13-May	Excellent
847	12-May	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	P. Tap Cart road	-	added	0	-	14-May	Excellent
848			2	Kasumpatti near SDA Complex Tank	-	added	0	-	14-May	Excellent
849			3	P.Tap Below Axis Bank SDA Complex	-	added	0	-	14-May	Excellent
850			4	Kasumpatti reservoir outlet	-	added	0	-	14-May	Excellent
851			5	Sanjauli reservoir outlet	-	added	0	-	14-May	Excellent

852			6	Sanjauli inlet Giri	-	added	0	-	14-May	Excellent
853			7	Sanjauli Inlet Gumma	-	added	5			suspicious(Not fit for