

**Water samples tested in Department of Microbiology IGMC, Shimla**

| Lab Sr. no. | Date   | Received through Email/Phone No.  | Daily Sr No. | Source                                    | Site | Na thiosulphate | PCC      | Final report (72Hrs) | Reported on | Result         |
|-------------|--------|---|--------------|---|------|-----------------|----------|----------------------|-------------|----------------|
| 1289        | 14-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1            | Public tap tibeti colony nabah            |      | added           | MPN= 40  | Citrobacter Spp.     |             | Unsatisfactory |
| 1290        |        |   | 2            | nabah supply nr. Shopping complex nabha   |      | added           | 0        | -                    |             | Excellent      |
| 1291        |        |   | 3            | phagli tank                               |      | added           | MPN= 13  | Citrobacter Spp.     |             | Unsatisfactory |
| 1292        |        |   | 4            | public tap nr sr. secondary school phagli |      | added           | 0        | -                    |             | Excellent      |
| 1293        |        |   | 5            | tube well no 2 untreated                  |      | NIL             | MPN=180+ | Klebsiella oxytoca   |             | Unsatisfactory |
| 1294        |        |   | 6            | tube well no 2 treated                    |      | NIL             | 0        | -                    |             | Excellent      |
| 1295        |        |   | 7            | kasumpti reserrior                        |      | added           | 0        | -                    |             | Excellent      |
| 1296        |        |   | 8            | sanjauli reserrior                        |      | added           | 0        | -                    |             | Excellent      |
| 1297        | 14-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1            | ridge tank shimla                         |      | added           | 0        | -                    |             | in process     |
| 1298        |        |   | 2            | mains field tank                          |      | added           | 0        | -                    |             | in process     |
| 1299        |        |   | 3            | bharari tank                              |      | added           | 0        | -                    |             | in process     |
| 1300        |        |   | 4            | dhalli tank                               |      | added           | 0        | -                    |             | in process     |
| 1301        |        |   | 5            | Chakkar tank                              |      | added           | 0        | -                    |             | in process     |
| 1302        |        |   | 6            | klollswood tank                           |      | added           | 0        | -                    |             | in process     |
| 1303        |        |   | 7            | Jakhu tank                                |      | added           | 0        | -                    |             | in process     |
| 1304        |        |   | 8            | vikasnagar tank                           |      | added           | 0        | -                    |             | in process     |
| 1305        |        |   | 9            | bowari shanan                             |      | NIL             | 0        | -                    |             | in process     |
| 1306        |        |   | 10           | handpump shanan                           |      | NIL             | 0        | -                    |             | in process     |
| 1307        |        |   | 11           | household 1 verma niwas shanan            |      | NIL             | 0        | -                    |             | in process     |
| 1308        |        |   | 12           | household 2 verma cottage shanan          |      | NIL             | 0        | -                    |             | in process     |

|      |        |   |   |   |   |       |          |                     |        |                |
|------|--------|---|---|---|---|-------|----------|---------------------|--------|----------------|
| 1309 | 15-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Tara mata mandir tank                                     | - | added | 0        | -                   | 17-Jul | Excellent      |
| 1310 |        |   | 2 | New Shimla Sec 3 tank(old)                                | - | added | MPN= 13  | Klebsiella spp.     | 17-Jul | Unsatisfactory |
| 1311 |        |   | 3 | Public tap,Negi Market,Sec 3,New Shimla                   | - | added | 0        | -                   | 17-Jul | Excellent      |
| 1312 |        |   | 4 | New Shimla Sec 3,tank(new)                                | - | added | 0        | -                   | 17-Jul | Excellent      |
| 1313 |        |   | 5 | Tube well no 2(UV)Ashwani Khad(Untreated water)           | - | NIL   | MPN= 160 | Citrobacter Spp.    | 17-Jul | Unsatisfactory |
| 1314 |        |   | 6 | Tube well no 2(UV)Ashwani Khad(treated water)             | - | NIL   | 0        | -                   | 17-Jul | Excellent      |
| 1315 |        |   | 7 | Kasumpati Reservoir                                       | - | added | 0        | -                   | 17-Jul | Excellent      |
| 1316 |        |   | 8 | Sanjauli Reservoir  | - | added | 0        | -                   | 17-Jul | Excellent      |
| 1317 | 16-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | North Oak (OH) Tank                                       | - | added | MPN=14   | Citrobacter koserii | 18-Jul | Unsatisfactory |
| 1318 |        |   | 2 | North Oak (UG) Tank                                       | - | added | 0        | -                   | 18-Jul | Excellent      |
| 1319 |        |   | 3 | Public tap chaulanti Road, Sanjauli, near Crift zone      | - | added | 0        | -                   | 18-Jul | Excellent      |
| 1320 |        |   | 4 | Public tap, sanjauli chowk                                | - | added | MPN=11   | Citrobacter spp.    | 18-Jul | Unsatisfactory |
| 1321 |        |   | 5 | Sanjauli reservoir  | - | added | 0        | -                   | 18-Jul | Excellent      |
| 1322 |        |   | 6 | Kasumpti Reservoir  | - | added | 0        | -                   | 18-Jul | Excellent      |
| 1323 |        |   | 7 | Tubewell no.2 (uv) untreated , Ashwani Khad               | - | Nil   | MPN=180+ | Klebsiella spp.     | 18-Jul | Unsatisfactory |
| 1324 |        |   | 8 | Tubewell no.2 (uv) treated , Ashwani khad                 | - | Nil   | MPN=13   | Pseudomonas spp.    | 18-Jul | Unsatisfactory |
| 1325 | 17-Jul | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | sanjauli reservoir  | - | added | MPN=180+ | -                   | 19-Jul | unsatisfactory |
| 1326 |        |   | 2 | Public tap Laxmi narayan mandir, sanjauli                 | - | added | MPN=5    | -                   | 19-Jul | in process     |
| 1327 |        |   | 3 | Dhingoo mandir tank (upper)                               | - | added | MPN=11   | -                   | 19-Jul | in process     |
| 1328 |        |   | 4 | Dhingoo mandir tank ( lower)                              | - | added | MPN=4    | -                   | 19-Jul | in process     |
| 1329 |        |   | 5 | Main supply ,tibetan colony, near malta niwas, Indu nagar | - | added | MPN=5    | -                   | 19-Jul | in process     |
| 1330 |        |   | 6 | Tubewell no.2 (uv) untreated water , Ashwani khad         | - | added | MPN=180  | -                   | 19-Jul | unsatisfactory |
| 1331 |        |   | 7 | tubewell no 2(uv) treated water, Ashwani khad             | - | nil   | MPN=5    | -                   | 19-Jul | in process     |
| 1332 |        |   | 8 | Kasumpti Reservoir  | - | added | 0        | -                   | 19-Jul | Excellent      |

|      |        |   |    |                             |   |       |          |   |        |                |
|------|--------|---|----|-----------------------------|---|-------|----------|---|--------|----------------|
| 1333 | 16-Jul | Samples received under hepatitis project community medicine igmc(HP) shimla | 1  | Ridge tank shimla           | - | added |          | - | 18-Jul | Excellent      |
| 1334 |        |   | 2  | mainsfield tank             | - | added |          | - | 18-Jul | Excellent      |
| 1335 |        |   | 3  | bharari tank                | - | added |          | - | 18-Jul | Excellent      |
| 1336 |        |   | 4  | Dhali tank                  | - | added |          | - | 18-Jul | Excellent      |
| 1337 |        |   | 5  | tavi tank                   | - | added |          | - | 18-Jul | Excellent      |
| 1338 |        |   | 6  | Knols wood tank             | - | added |          | - | 18-Jul | Excellent      |
| 1339 |        |   | 7  | Jakhu tank                  | - | added |          | - | 18-Jul | Excellent      |
| 1340 |        |   | 8  | Vikasnagar tank             | - | added |          | - | 18-Jul | Excellent      |
| 1341 |        |   | 9  | Hand pump lakkar bazar      | - | nil   | MPN=3    | - | 18-Jul |                |
| 1342 |        |   | 10 | Primary school jakhu        | - | nil   |          | - | 18-Jul | Excellent      |
| 1343 |        |   | 11 | Bhnnie Bone building jakhu  | - | nil   |          | - | 18-Jul | Excellent      |
| 1344 |        |   | 12 | Titla house jakhu           | - | nil   |          | - | 18-Jul | Excellent      |
| 1345 | 17-Jul | Samples received under hepatitis project community medicine igmc(HP) shimla | 1  | Ridge tank shimla           | - | added |          | - | 19-Jul | Excellent      |
| 1346 |        |   | 2  | Mains field tank            | - | added |          | - | 19-Jul | Excellent      |
| 1347 |        |   | 3  | Keleston tank               | - | added |          | - | 19-Jul | Excellent      |
| 1348 |        |   | 4  | Dhali tank                  | - | added |          | - | 19-Jul | Excellent      |
| 1349 |        |   | 5  | Chakkar tank                | - | added |          | - | 19-Jul | Excellent      |
| 1350 |        |   | 6  | Phase 3                     | - | added | MPN=1    | - | 19-Jul |                |
| 1351 |        |   | 7  | Jakhu tank                  | - | added |          | - | 19-Jul | Excellent      |
| 1352 |        |   | 8  | Kusumpati tank              | - | added |          | - | 19-Jul | Excellent      |
| 1353 |        |   | 9  | Hand pump chalaunthi        | - | added | MPN=50   | - | 19-Jul | unsatisfactory |
| 1354 |        |   | 10 | Chau\launthi bavri          | - | added | MPN=180+ | - | 19-Jul | unsatisfactory |
| 1355 |        |   | 11 | Simran house lower khalini  | - | nil   |          | - | 19-Jul | Excellent      |
| 1356 |        |   | 12 | Kaushal niwas lower khalini | - | nil   |          | - | 19-Jul | Excellent      |