

Lab Sr. No.	Date	Received through Email/Phone no.	Daily Sr. No.	Source	Sodium Thiosulphat	Final Report (72 hours)	Final Reporting Date	Result	
5005	5/10/2019	Samples received from Assisstant Engineer, Shimla Jal Prabandhan Nigam Ltd.	1	KASUMPATI RESERVOIR	added	Thermotolerant E.coli not detected	8/10/2019	Excellent	
5006			2	P.TAP NEAR GOEL APARTMENT	added	E.coli not	8/10/2019	Satisfactory	
5007			3	P.TAP NEAR LAXMI NARAYAN TEMPLE SANJAULI	added	Thermotolerant E.coli not	8/10/2019	Satisfactory	
5008			4	P.TAP NEAR SANJAULI CHOWK	added	E.coli not	8/10/2019	Excellent	
5009			5	ENGINE GHAR TANK	added	E.coli not	8/10/2019	Satisfactory	
5010			6	SANJAULI RESERVOIR	added	E.coli not	8/10/2019	Unsatisfactory	
5011			7	NORTH OAK UG TANK	added	Thermotolerant E.coli not	8/10/2019	repeat sample requested	
5012			8	NORTH OAK OH TANK	added	Thermotolerant E.coli not	8/10/2019	repeat sample requested	
5013	5/10/2019			1	Ridge tank	added	Thermotolerant E.coli not detected	7/10/2019	
5014				2	Mainsfield tank	added	E.coli not	7/10/2019	
5015			3	Kelaston tank	added		7/10/2019	Excellent	
5016			4	Dhalli tank	added		7/10/2019		
5017			5	P.tap Yadgar	added		7/10/2019		
5018			6	Phase-3 tank	added		7/10/2019	Unsatisfactory	
5019			7	Jakhoo tank ropeway	added		7/10/2019		
5020			8	P.tap Brock Hurst Chotta Shimla	added		7/10/2019	Unsatisfactory	
5021			9	P.tap Brock Hurst-2 Chotta Shimla	added		7/10/2019	Unsatisfactory	
5022			10	P.tap Apna medical store	added		7/10/2019	Unsatisfactory	
5023			11	P.tap near Police Gumati	added		7/10/2019		
5024			12	P.tap servant quarter	added		7/10/2019		
5025	6/10/2019	Samples received	1	KASUMPATI RESERVOIR	added	E.coli not	9/10/2019	Excellent	
5026			2	P.TAP NEAR MC OFFICE NEW SHIMLA (REPEAT)	added	Thermotolerant E.coli not	9/10/2019	Excellent	
5027			3	SECT-2 TANK (REPEAT)	added	E.coli not	9/10/2019	Excellent	
5028			4	SECT-3 OLD TANK	added	E.coli not	9/10/2019	Excellent	
5029			5	P.TAP NEAR KRANTI CHOWK	added	E.coli not	9/10/2019	Excellent	
5030			6	SECT-3 NEW TANK	added	E.coli not	9/10/2019	Excellent	
5031			7	P.TAP NEAR MANGALA BHAWAN	added	E.coli not	9/10/2019	Excellent	

5032			8	SANJAULI RESERVOIR	added	E.coli not	9/10/2019	Excellent
5033	7/10/2019	Samples received	1	KASUMPATI RESERVOIR	added			in process
5034			2	P.TAP NEAR KHALINI CHOWK	added			in process
5035			3	P.TAP NEAR BY PASS KHALINI	added			in process
5036			4	P.TAP NEAR PANCHIATHA	added			in process
5037			5	SUPPLY NEAR SOOD BHAWAN BHAGWATI NAGAR(RPEAT)	added			in process
5038			6	P.TAP NEAR KALI MAATA MANDIR BHAGWATI NAGAR (REPEATO	added			in process
5039			7	KNOLLSWOOD TANK	added			in process
5040			8	SANJAULI RESERVOIR	added			in process
5041	7/10/2019	Samples received un	1	Ridge tank	added			###
5042			2	Mainsfield tank	added			### Unsatisfactory
5043			3	Kelaston tank	added			### Unsatisfactory
5044			4	Dhalli tank	added			### Unsatisfactory
5045			5	P.tap yadgar	added			###
5046			6	Knollswood tank	added			### Unsatisfactory
5047			7	Jakhoo tank ropeway	added			### Unsatisfactory
5048				P.tap brock hurst	added			###
5049				P.tap charley mount	added			### Unsatisfactory
5050				P.tap lehnu bhawan	added			### Unsatisfactory
5051				P.tap prasspact lodge	added			### Unsatisfactory