Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
3581	17/7/19	Samples received from Assistant Engineer, Shimla Jal	1	Kasumpti Reservoir	added	MPN =35	thermotolerant E.coli not	20-7-19	Repeat sample requested
3582			2	Advance study tank Summer hill	added	MPN = 1	thermotolerant E.coli not	20-7-19	satisfactory
3583			3	Summer hill Bazar tank	added	MPN = 4	thermotolerant E.coli not	20-7-19	Repeat sample requested
3584			4	P.Tap near Raj Dairy, summer hill	added	MPN =7	thermotolerant E.coli not	20-7-19	Repeat sample requested
3585			5	P.TAP NEAR LOWER SUMMER HILL	added	MPN =3	thermotolerant E.coli not	20-7-19	satisfactory
3586			6	p. tap near summer hill	added	MPN =0	_	19-7-19	EXCELLENT
3587			7	supply near post office chowra maidan	added	MPN =1	thermotolerant E.coli not	20-7-19	satisfactory
3588			8	sanjauli reservoir	added	MPN = 0	_	19-7-19	EXCELLENT
3589	17-07-19	Samples Received under Hepatitis Project Community	1	Ridge tank	added	MPN = 0			EXCELLENT
3590			2	mains field tank	added	MPN =0			EXCELLENT
3591			3	Kalaston Tank	added	MPN=1			in process
3592			4	Dhalli tank	added	MPN=2			in process
3593			5	Pub-tap totu chowk	added	MPN=180+			Unstisfactory
3594			6	Knollswood tank	added	MPN=5			in process
3595			7	Jakhu tank ropeway	added	MPN=6			in process
3596			8	Pub-tap khalini	added	MPN=6			in process
3597			9	Pub-tap prabha khan store	added	MPN=35			Unstisfactory
3598			10	Pub-tap suji lane	added	MPN=5			in process
3599			11	Pub-tap pursharthi basti	added	MPN =0			EXCELLENT
3600			12	Pub-tap indira chowk	added	MPN=5			in process