

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
4337	29/8/2019	Samples received from Assistant Engineer, Shimla Jal	1	KASUMPATI RESERVOIR	added	MPN=1	thermotolerant E.coli not detected	09-01-2019	satisfactory
4338			2	SECT-2 TANK	added	MPN=1	thermotolerant E.coli not detected	09-01-2019	satisfactory
4339			3	SECT-4 TANK	added	MPN=0	thermotolerant E.coli not detected	09-01-2019	excellent
4340			4	SECT - 3 OLD TANK OUTLET	added	MPN=180	thermotolerant E.coli not detected	09-01-2019	Adv: Repeat sample requested
4341			5	P.TAP NEAR KRANTI CHOWK	added	MPN=3	thermotolerant E.coli not detected	09-01-2019	satisfactory
4342			6	SECT-3 NEW TANK	added	MPN=50	thermotolerant E.coli not detected	09-01-2019	Adv: Repeat sample requested
4343			7	P.TAP NEAR MANGLA BHAWAN	added	MPN=9	thermotolerant E.coli not detected	09-01-2019	Adv: Repeat sample requested
4344			8	SANJAULI RESERVOIR	added	MPN=10	thermotolerant E.coli not detected	09-01-2019	Adv: Repeat sample requested
4345	29/8/2019	Samples Received under Hepatitis Project Community	1	RIDGE TANK	added	MPN=2		31-8-19	
4346			2	MAINS FIELD TANK	added	MPN=1		31-8-19	
4347			3	Kelaston tank	added	MPN=1		31-8-19	
4348			4	Dhalli tank	added	MPN=2		31-8-19	
4349			5	Chakkar tank	added	MPN=5		31-8-19	
4350			6	Knowllswood tank	added	MPN=20		31-8-19	unsatisfactory
4351			7	Jakhu ropeway tank	added	MPN=1		31-8-19	
4352			8	VIKASNAGAR TANK	added	MPN=3		31-8-19	
4353			9	POLIVE LINE(PT) BHARARI	added	MPN=4		31-8-19	
4354			10	BABLI KARYANA MASHOBRA(PT)	added	MPN=3		31-8-19	
4355			11	NR DEPO MASHOBRA(PT)	added	MPN=1		31-8-19	
4356			12	NR POST OFFICE MASHOBRA(PT)	added	MPN=1		31-8-19	
4357	30/8/19	Samples received from Assistant Engineer, Shimla Jal	1	KASUMPATI RESERVOIR	added	MPN=3	thermotolerant E.coli not detected	09-02-2019	Satisfactory
4358			2	P.TAP NEAR DURGA COTTAGE SDA	added	MPN=0	thermotolerant E.coli not detected	09-02-2019	in process
4359			3	SDA KASUMPATI TANK	added	MPN=0	thermotolerant E.coli not detected	09-02-2019	in process

4360			4	P.TAP NEW SENKUT QUARTER KNOLLSWOOD	added	MPN=0	thermotolerant E.coli not detected	09-02-2019	in process
4361			5	P.TAP NEAR POLICE GUMTI CHOTTA SHIMLA	added	MPN=0	thermotolerant E.coli not detected	09-02-2019	in process
4362			6	P.TAP NEAR APNA MEDICAL STORE CHOTTA SHIMLA	added	MPN=3	thermotolerant E.coli not detected	09-02-2019	Satisfactory
4363			7	P.TAP NEW KHADI BHANDAR MALL ROAD (repeat0	added	MPN=0	thermotolerant E.coli not detected	09-02-2019	in process
4364			8	SANJAULI RESERVOIR	added	MPN=0	thermotolerant E.coli not detected	09-02-2019	in process
4365	30/8/19	Samples Received under Hepatitis Project Community	1	Ridge Tank	added	MPN=1		09-01-2019	
4366			2	Pub-tap HPMC ridge	added	MPN=2		09-01-2019	
4367			3	Pub-tap UCO bank dhalli	added	MPN=0		09-01-2019	excellent
4368			4	Dhali Tank	added	MPN=0		09-01-2019	excellent
4369			5	Pub-tap yadgar	added	MPN=0		09-01-2019	excellent
4370			6	Pub-tap totu chowk	added	MPN=0		09-01-2019	excellent
4371			7	Jakhu tank ropeway	added	MPN=0		09-01-2019	excellent
4372			8	VIKASNAGAR TANK	added	MPN=1		09-01-2019	
4373			9	Pub-tap near SBI ATM totu	added	MPN=0		09-01-2019	excellent
4374			10	Pub-tap near fullu bhawan dhanda	added	MPN=1		09-01-2019	
4375			11	Pub-tap near kamal bhawan dhanda	added	MPN=1		09-01-2019	
4376			12	Pub-tap near SBI ATM dhanda	added	MPN=1		09-01-2019	
4377	31/08/2019	Samples received from Assistant Engineer, Shimla Jal	1	Kasumpti Reservoir	added				in process
4378			2	Bangala Colony tank (Repeat)	added				in process
4379			3	public tap near Bharari temple	added				in process
4380			4	supply near Bhalla Niwas, Bhrari	added				in process
4381			5	public tap near police colony Bharari	added				in process
4382			6	public tap near police ground Bharari	added				in process
4383			7	Bharari tank	added				in process
4384			8	Sanjauli Reservoir	added				in process
4385	31/8/19	Samples Received under Hepatitis Project Community	1	Pub-tap Ridge HPMC	added	MPN=12			in process
4386			2	Pub-tap near controle room IPH ridge	added	MPN=04		09-02-2019	

4387			3	Kalaston Tank	added	MPN=0		09-02-2019	excellent
4388			4	Dhalli tank	added	MPN=05		09-02-2019	
4389			5	phase-3 tank	added	MPN=08		09-02-2019	
4390			6	Pub-tap green valley	added	MPN=20		09-02-2019	unsatisfactory
4391			7	Jakhu tank ropeway	added	MPN=02		09-02-2019	
4392			8	VIKASNAGAR TANK	added	MPN=180+		09-02-2019	unsatisfactory
4393			9	Pub-tap brock host-1	added	MPN=05		09-02-2019	
4394			10	Pub-tap brokhost-2	added	MPN=09		09-02-2019	
4395			11	Pub-tap brock host near servant quarter	added	MPN=12		09-02-2019	
4396			12	Pub-tap chintpurni chowk	added	MPN=11		09-02-2019	
4397	09-01-2019	Samples received from Assistant Engineer, Shimla	1	Kasumpti reservoir	added	MPN = 0	thermotolerant E.coli not detected	09-03-2019	EXCELLENT
4398			2	Summer hill Bazar tank(Repeat)	added	MPN = 1	thermotolerant E.coli not detected	09-03-2019	SATISFACTORY
4399			3	Public tap near Raj Dairy Summer hill (Repeat)	added	MPN =1	thermotolerant E.coli not detected	09-03-2019	SATISFACTORY
4400			4	Public tap near lower Summer hill (Repeat)	added	MPN =0	thermotolerant E.coli not detected	09-03-2019	EXCELLENT
4401			5	Kamna devi tank	added	MPN =0	thermotolerant E.coli not detected	09-03-2019	EXCELLENT
4402			6	Supply near 18 family CPWD quarter Boileauganj	added	MPN =0	thermotolerant E.coli not detected	09-03-2019	EXCELLENT
4403			7	Sandale tank Chakkar	added	MPN =1	thermotolerant E.coli not detected	09-03-2019	SATISFACTORY
4404			8	Sanjauli reservoir	added	MPN =0	thermotolerant E.coli not detected	09-03-2019	EXCELLENT