

**RESULTS OF BACTERIOLOGICAL SAMPLES RECEIVED ON DATED 17-11-2020**

Sr. No.	Collection Date	Lab. Code	Location of Sample taken	ANALYSIS RESULTS		Final Reporting Date
				Total Coliform MPN/100 ml	E.Coli MPN/100 ml	
1	17.11.2020	1041	Kasumpati Reservoir	<1.1	not required	20.11.2020
2		1042	SDA Kasumpti Tank	<1.1	not required	20.11.2020
3		1043	Phase 3 TANK NO 1	<1.1	not required	20.11.2020
4		1044	P Tap near Panchiatta	<1.1	not required	20.11.2020
5		1045	Supply near Sood bhawan, bhagwati nagar Khalini	<1.1	not required	20.11.2020
6		1046	P Tap near Bypass Road Khalini	<1.1	not required	20.11.2020
7		1047	P Tap near Khalini chowk	<1.1	not required	20.11.2020
8		1048	Knallswood Tank	<1.1	not required	20.11.2020
9		1049	P Tap near Servent Quarter Knallswood	<1.1	not required	20.11.2020
10		1050	P Tap near Police Gumti Chota Shimla	<1.1	not required	20.11.2020
11		1051	P Tap near Brock Hurst	<1.1	not required	20.11.2020
12		1052	Mainsfield Tank	<1.1	not required	20.11.2020
13		1053	103 Tank	<1.1	not required	20.11.2020
14		1054	Chakkar Tank	<1.1	not required	20.11.2020
15		1055	Phagli Tank	<1.1	not required	20.11.2020
16		1056	Bharari Tank	<1.1	not required	20.11.2020
17		1057	Sanjauli Reservoir	<1.1	not required	20.11.2020
18		1058	Giri Inlet	<1.1	not required	20.11.2020
19		1059	Gumma Inlet	<1.1	not required	20.11.2020
20		1060	Dhalli Tank Outlet	<1.1	not required	20.11.2020