

**RESULTS OF BACTERIOLOGICAL SAMPLES RECEIVED ON DATED 23-11-2020**

Sr. No.	Collection Date	Lab. Code	Location of Sample taken	ANALYSIS RESULTS		Final Reporting Date
				Total Coliform MPN/100 ml	E.Coli MPN/100 ml	
1	23.11.2020	1161	Kasumpti Reservior	<1.1	Not Required	26-11-20
2		1162	Phase -III Tank	<1.1	Not Required	26-11-20
3		1163	BhimaKali Tank	<1.1	Not Required	26-11-20
4		1164	Phagli Tank	<1.1	Not Required	26-11-20
5		1165	P. Tap near Goel Appartment, Dhingu	<1.1	Not Required	26-11-20
6		1166	Dhingu Mandir Tank	12	<1.1	26-11-20
7		1167	Dhalli Tank Outlet	<1.1	Not Required	26-11-20
8		1168	P. tap near Laxmi Narayan Temple Sanjauli	<1.1	Not Required	26-11-20
9		1169	P. Tap Near old Police Thana Sanjauli.	<1.1	Not Required	26-11-20
10		1170	Engine Ghar Tank	<1.1	Not Required	26-11-20
11		1171	P. Tap near Mehta Parking	<1.1	Not Required	26-11-20
12		1172	Bangala Colony Tank	<1.1	Not Required	26-11-20
13		1173	P. Tap near Bangala Tank	<1.1	Not Required	26-11-20
14		1174	North Oak UG Tank	<1.1	Not Required	26-11-20
15		1175	North Oak OH Tank	16	<1.1	26-11-20
16		1176	P. Tap near MC Office, Shimla	<1.1	Not Required	26-11-20
17		1177	Sanjauli Reservior	<1.1	Not Required	26-11-20
18		1178	Giri Inlet	<1.1	Not Required	26-11-20
19		1179	Gumma Inlet	<1.1	Not Required	26-11-20
20		1180	Mainsfield Tank	<1.1	Not Required	26-11-20